

Site Name: Culvert Hwy 197 Stream Name: Peacock Creek Structure Owner: California Department of Transportation Year Remediated: 2013 Site Type: Road crossing Site Status After Remediation: Remediated, fish response unconfirmed Species Benefited After Remediation: Multiple Andromous Salmonids

Immediate Downstream barrier PAD ID:

*Site statistics based on December 2014 version of the Passage Assessment Database
Tributary To: Smith River
Barrier Remediation By:CalTrans, Division of Environmental Analysis
Barrier Description Prior to Remediation: Partial
Count of Barriers Downstream: 0
Count of Barriers Upstream: 0
Distance Upstream to Next Barrier or Limit of Anadromy: 4.23819 mi

Notes: In April 2013, the jump at outlet was notched and redwood baffles were replaced with steel baffles. Before: Partial barrier per FishXing Software per CDFW. Listed as partial barrier to adult coho, total barrier to upstream juveniles. The Peacock Creek culvert provides good passage for adult anadromous salmonids and the culvert barrel is predicted to provide some passage for resident trout and juvenile salmonids. However, the outlet weir is perched almost 0.5 ft above the natural tailwater control creating a leap that impedes upstream migration of resident trout and juvenile salmonids. The leap at the outlet weir should be addressed to enhance passage for resident trout and juvenile salmonids. The wood-block weir performance and condition should be monitored as the blocks are in fair-to-poor condition. Metal arch culvert under North Bank Road, 15' wide at base x 7' high x 75' long with railroad tie baffles and a stilling pool at the outfall of the culvert. Main concern is excessive summer water extraction.