



- Barrier Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed



After Photo
Not Available

Site Name: Glen Oaks Dam
Stream Name: Stuart Creek
Structure Owner:
Year Remediated: 2014
Site Type: Road crossing
Site Status After Remediation: Remediated, fish response unconfirmed
Species Benefited After Remediation:
Immediate Downstream barrier PAD ID: [712577](#)

PAD ID: [712580](#)
Tributary To: Calabazas Creek
Barrier Remediation By: Sonoma Land Trust
Barrier Description Prior to Remediation: Total
Count of Barriers Downstream: 4
Count of Barriers Upstream: 3
Distance Upstream to Next Barrier or Limit of Anadromy : 0.45432 Miles

*Site statistics based on June 2015 version of the Passage Assessment Database

Notes: In 2014, the spillway was lowered and the notch was widened to provide upstream adult passage and improve passage for juveniles. This project opened up 1 mile of high quality steelhead habitat upstream. There is a 12-foot waterfall 1 mile upstream that blocks anadromy. Before: RED filter result. Total barrier per DFG Restoration Manual per Sonoma Ecology Center.