

- Barrier Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed



Photo Credit:US Forest Service




Photo Credit:US Forest Service

*Site statistics based on June 2015 version of the Passage Assessment Database

Site Name: Rock and mortar dam with spillway

Stream Name: Arroyo Trabuco

Structure Owner: U.S. Forest Service

Year Remediated: 2014

Site Type: Dam

Site Status After Remediation: Remediated, fish response unconfirmed

Species Benefited After Remediation:

Immediate Downstream barrier PAD ID:

PAD ID: 758694

Tributary To: San Juan Creek

Barrier Remediation By:U.S. Forest Service

Barrier Description Prior to Remediation:Total

Count of Barriers Downstream:

Count of Barriers Upstream:

Distance Upstream to Next Barrier or Limit of Anadromy : Miles

Notes: In December 2014, the Cleveland National Forest in conjunction with the Tahoe Mine Reclamation Creek removed this dam. Before: Total barrier per field survey conducted by USFS. 2013 USFS survey comments: Rock and mortar 6' H x 5.5' W x 31' L dam with spillway, condition: Good. Dam caused cascade over boulders with shallow outlet pool Has head gate that is obstructed by boulders, wing walls tie into road prism Dams are planned for removal. Removal of dams will likely be completed between 2017- 2019.