

- Barrier Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed



Photo Credit:US Forest Service




Photo Credit:US Forest Service

*Site statistics based on June 2015 version of the Passage Assessment Database

Site Name: Rock and mortar fill between bedrock and boulder (removed)

PAD ID: [758697](#)

Stream Name: Arroyo Trabuco

Tributary To: San Juan Creek

Structure Owner: U.S. Forest Service

Barrier Remediation By:U.S. Forest Service

Year Remediated: 2014

Barrier Description Prior to Remediation:Total

Site Type: Dam

Count of Barriers Downstream:

Site Status After Remediation: Remediated, fish response unconfirmed

Count of Barriers Upstream:

Species Benefited After Remediation: Steelhead

Distance Upstream to Next Barrier or Limit of Anadromy : Miles

Immediate Downstream barrier PAD ID:

Notes: In December 2014, the Cleveland National Forest in conjunction with the Tahoe Mine Reclamation Crew removed this dam. Before: Total barrier per field survey conducted by U.S. Forest Service. 2013 USFS survey comments: Rock and mortar fill (2.5' h x 2.5' w) between bedrock and boulder , condition: Fair. Juvenile barrier Built between bedrock and Large boulders Dams are planned for removal. Removal of dams will likely be completed between 2017- 2019.