



- Barrier Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed



Photo Credit:US Forest Service



Photo Credit:US Forest Service

**Site Name:** Tenaja Falls Trail low flow concrete crossing (removed)

**Stream Name:** San Mateo Creek

**Structure Owner:** U.S. Forest Service

**Year Remediated:** 2012

**Site Type:** Road crossing

**Site Status After Remediation:** Remediated, fish response unconfirmed

**Species Benefited After Remediation:** Steelhead

**Immediate Downstream barrier PAD ID:**

**PAD ID:** 758769

**Tributary To:** Pacific Ocean

**Barrier Remediation By:**U.S. Forest Service

**Barrier Description Prior to Remediation:**Unknown

**Count of Barriers Downstream:**

**Count of Barriers Upstream:**

**Distance Upstream to Next Barrier or Limit of Anadromy :** Miles

\*Site statistics based on June 2015 version of the Passage Assessment Database

**Notes:** Concrete crossing was removed in October 2012 restoring 3.5 miles of stream and habitat for endangered southern steelhead and other sensitive aquatic organisms. San Mateo Creek is a historical fishery for steelhead trout. Before: Hardened crossing on the Tenaja Falls Trail in the Cleveland National Forest that crosses San Mateo Creek and impedes passage of aquatic organisms.