

ASBESTOS NOTIFICATION

The purpose of this document is to notify employees, building tenants, contractors and vendors of the presence and location of building materials which contain or are assumed to contain asbestos within the following building:

Water Resources Building (#018) 1416 9th Street, Sacramento

GENERAL DISCUSSION

Asbestos is not harmful unless asbestos fibers become airborne due to material deterioration or damage. The building materials which contain or are assumed to contain asbestos identified in this building were generally in good condition and are not likely to release asbestos fibers unless disturbed. It is important to take the following precautions to minimize the potential for disturbing building materials.

- Assume all building materials contain asbestos unless otherwise determined through laboratory analysis;
- Do not drill holes, sand, cut, grind or otherwise disturb building materials;
- Do not access above ceilings, behind walls or other locations;
- Do not disturb damaged building materials; and
- Immediately report to the Building Manager any damaged building material. Only authorized and properly trained personnel shall perform repair, removal and cleanup.

Suspected building materials from various locations throughout the building have been tested. Such testing has resulted in asbestos being "None Detected" for those specific materials/locations identified. In most cases, the number of samples collected and analyzed is sufficient to make a determination of asbestos content for that particular material in that particular location, yet not sufficient to make the determination that the material is "None Detected" for the entire building. For the purposes of this notification, these materials will be listed as "Assumed Positive" until sufficient sampling and analysis determines otherwise.

For further information regarding specific location or specific suspect material testing please contact the Building and Property Management Building Manager.

MATERIALS WHICH CONTAIN OR ARE ASSUMED TO CONTAIN ASBESTOS

Building materials commonly excluded from being suspected for containing asbestos include but are not limited to: unwrapped pink and yellow fiberglass insulating materials or products, foam insulation, bare concrete, wood, metal, plastic, or glass. All other types of building materials or coatings on such materials are commonly listed as "suspect asbestos-containing" material and must be assumed to contain asbestos unless otherwise tested.

The type(s) and location(s) of building materials which contain or are assumed to contain asbestos within this building are as follows:

Material: **Thermal System Insulation (TSI)** Lab Result: **Tested Positive**

Location(s): **On Piping, Vessels & Tanks - Mechanical Rooms and Above Ceilings & Behind Walls - Throughout**

ASBESTOS NOTIFICATION

Water Resources Building (#018) 1416 9th Street, Sacramento

Material: Fireproofing Lab Result: Tested Positive

Location(s): On Structural Components Above Ceilings & Behind Walls - Throughout

Material: Suspended 2'x4' Ceiling Tiles Lab Result: Tested Positive

Location(s): Throughout

Material: Gypsum/Joint Compound Lab Result: Assumed Positive

Location(s): Walls & Ceilings - Throughout

Material: Base Cove Adhesive Lab Result: Tested Positive

Location(s): Walls - Throughout

Material: Vinyl Floor Tile with Mastic Backing Lab Result: Tested Positive

Location(s): Throughout

Material: Vinyl Sheet Flooring with Mastic Backing Lab Result: Assumed Positive

Location(s): Throughout

Material: Carpet Adhesive Lab Result: Assumed Positive

Location(s): Throughout

Material: Ceramic Tile Grout Lab Result: Assumed Positive

Location(s): Throughout

Material: Roof Membrane and Mastic Sealants Lab Result: Tested Positive

Location(s): Roofs - Throughout

Material: Fire Doors Lab Result: Assumed Positive

Location(s): Throughout

MATERIALS TESTED AND FOUND "NONE DETECTED" FOR ASBESTOS

The below listed material(s) have been determined through sufficient sampling and laboratory analysis to be "None Detected" for asbestos and are as follows:

Material: Plaster Lab Result: None Detected

Location(s): Throughout