

-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated
- Non-Jurisdictional Lines**
-  Erosional





Figure 8, Page 151 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated
- RWQCB Aquatic Resources**
-  Ditch/Canal





Figure 8, Page 152 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated
- RWQCB Aquatic Resources**
-  Ditch/Canal
-  Roadside Ditch
- Non-Jurisdictional Lines**
-  Erosional



Figure 8, Page 153 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





M129-T1 35.262943, -115.497784

M123-T5

M123-T4

35.25818, -115.50395

-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated




Figure 8, Page 154 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





 Survey Area
USACE and RWQCB Aquatic Resources
 Streambed Unvegetated




Figure 8, Page 155 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
 TRANSMISSION LINE REMEDIAL
 ACTION SCHEME PROJECT
 AQUATIC RESOURCES DELINEATION



-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated



35.27181,
-115.485264

M130-T1

M130-T2

35.274574,
-115.481403



Figure 8, Page 156 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION



-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated





Figure 8, Page 157 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





 Survey Area
USACE and RWQCB Aquatic Resources
 Streambed Unvegetated

35.289275,
-115.46014

M1E1-T4

M1E1-T3

35.284355,
-115.467887

M1E1-T2



Figure 8, Page 158 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





35.291785,
-115.457484

M1E2-T1

M1E2-T2

35.294305,
-115.453151

-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated



Figure 8, Page 159 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated



Figure 8, Page 160 of 189


USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION






M133-T4 35.30665,
-115.436859



M133-T3



M133-T2



35.301647,
-115.442986

-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Vegetated



Figure 8, Page 161 of 189
USACE and RWQCB Aquatic Resources Survey Results
 LUGO-VICTORVILLE 500-KV TRANSMISSION LINE REMEDIAL ACTION SCHEME PROJECT
 AQUATIC RESOURCES DELINEATION





-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated



Figure 8, Page 162 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





 Survey Area
USACE and RWQCB Aquatic Resources
 Streambed Unvegetated

35.32021,
-115.417135

M135-T1

M134-T4

M134-T3

35.315383,
-115.424681




Figure 8, Page 163 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





 Survey Area
USACE and RWQCB Aquatic Resources
 Streambed Unvegetated






Figure 8, Page 164 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
 TRANSMISSION LINE REMEDIAL
 ACTION SCHEME PROJECT
 AQUATIC RESOURCES DELINEATION



-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated



M186-T2 35.332731,
-115.400581

M186-T1

35.329406,
-115.404379



Figure 8, Page 165 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION



○ Survey Area
USACE and RWQCB Aquatic Resources
● Streambed Unvegetated





Figure 8, Page 166 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION



Survey Area
USACE and RWQCB Aquatic Resources
Streambed Unvegetated

M187-12 35.342826,
-115.386528



M187-11

35.339548,
-115.390262






Figure 8, Page 167 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- USACE and RWQCB Aquatic Resources**
- Streambed Unvegetated

M133-T3
35.3529,
-115.37167

M133-T2
53 51
52

M133-T1
35.348072,
-115.379191





Figure 8, Page 168 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





 Survey Area
USACE and RWQCB Aquatic Resources
 Streambed Unvegetated




Figure 8, Page 169 of 189


USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
 TRANSMISSION LINE REMEDIAL
 ACTION SCHEME PROJECT
 AQUATIC RESOURCES DELINEATION



-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated
- Non-Jurisdictional Lines**
-  Paleo Channel

M189-T3
35.364191,
-115.356771



M189-T2

35.360777,
-115.360701





Figure 8, Page 170 of 189


USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION




-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated

M140-T2 35.369755,
-115.349016



M140-T1



35.366297,
-115.353006



Figure 8, Page 171 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION



-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated
- Non-Jurisdictional Lines**
-  Erosional

M140-T4 35.37523,
-115.341385



M140-T3



35.371862,
-115.345249



Figure 8, Page 172 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated




Figure 8, Page 173 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated



Figure 8, Page 174 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION



-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated




Figure 8, Page 175 of 189
USACE and RWQCB Aquatic Resources Survey Results
 LUGO-VICTORVILLE 500-KV TRANSMISSION LINE REMEDIAL ACTION SCHEME PROJECT
 AQUATIC RESOURCES DELINEATION



-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated
- Non-Jurisdictional Lines**
-  Paleo Channel

M143-T2 35.39925,
-115.307883



M143-T1



35.39611,
-115.311433



Figure 8, Page 176 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION



○ Survey Area
USACE and RWQCB Aquatic Resources
● Streambed Unvegetated




Figure 8, Page 177 of 189
USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION



-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated




Figure 8, Page 178 of 189


USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION




-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated

M145-T1 35.41553,
-115.285158



M144-T3



35.412137,
-115.289063




Figure 8, Page 179 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated



Figure 8, Page 180 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Vegetated

M146-T1
35.426291,
-115.270128

M145-T4

35.422926,
-115.273997



Figure 8, Page 181 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION



-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated
- Non-Jurisdictional Lines**
-  Paleo Channel

M146-T3 35.431535,
-115.262801



M146-T2



35.428234,
-115.266583



Figure 8, Page 182 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated
- Non-Jurisdictional Lines**
-  Paleo Channel

M147-T2 35.436508,
-115.255852

M147-T1

35.433279,
-115.259534




Figure 8, Page 183 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION



-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated



35.438853,
-115.25254

M147-T3

35.441818,
-115.247274

M147-T4

M147-T4




Figure 8, Page 184 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Vegetated



Figure 8, Page 185 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION



-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Vegetated
- RWQCB Aquatic Resources**
-  Basin






Figure 8, Page 186 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Vegetated




Figure 8, Page 187 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Vegetated

M150-T1
35.463115,
-115.217434

M150-T1

M149-T4

35.460325,
-115.222514



Figure 8, Page 188 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- USACE and RWQCB Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Vegetated



Figure 8, Page 189 of 189

USACE and RWQCB Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





 Survey Area



Figure 9, Page 1 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Ditch/Canal
-  Ditch/Canal - Bank




Figure 9, Page 2 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- CDFW Aquatic Resources**
- Ditch/Canal
- Ditch/Canal - Bank
- Streambed Unvegetated
- Streambed Unvegetated - Bank



Figure 9, Page 3 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Ditch/Canal
-  Ditch/Canal - Bank
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank




Figure 9, Page 4 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 5 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 6 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Ditch/Canal
- Ditch/Canal - Bank
- Streambed Unvegetated
- Streambed Unvegetated - Bank

1347700E 1347701E 1347702E 1347703E 1347704E 1347705E 1347706E 1347707E

2151065E

34.849017,
-116.822974

34.848674,
-116.814548




Figure 9, Page 7 of 189

CDFW Aquatic Resources Survey Results


LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION






- Survey Area
- CDFW Aquatic Resources**
- Ditch/Canal
- Ditch/Canal - Bank
- Streambed Unvegetated
- Streambed Vegetated
- Streambed Vegetated - Bank

1847709E



34.848636,
-116.813564

1847710E,
4045427E



2347287E



2347286E



2347285E



2347284E



2347283E



2347282E



2347281E



2347280E



34.848119,
-116.805388





Figure 9, Page 8 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Ditch/Canal
-  Ditch/Canal - Bank

2347279E 2347278E 2347276E 2347275E 2347274E 2347273E 2347272E 2347271E 2347270E 2347269E

34.84808,
-116.804495

34.847756,
-116.796546




Figure 9, Page 9 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
 TRANSMISSION LINE REMEDIAL
 ACTION SCHEME PROJECT
 AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Ditch/Canal
-  Ditch/Canal - Bank
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

2347268E



34.847721,
-116.795669

2347266E



2347265E



2347264E



2347263E,
4169402E

2313467E,
2347262E



2313466E,
2347261E



2313465E,
2347260E

2347259E



4632664E



34.847071,
-116.788007



Figure 9, Page 10 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Ditch/Canal
-  Ditch/Canal - Bank

2347257E



34.846956,
-116.787234

2347256E



2347255E



2347254E



2347253E



2347252E



2347251E



2361391E



2361390E



2361389E



2361388E



34.845697,
-116.779057




Figure 9, Page 11 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Ditch/Canal
-  Ditch/Canal - Bank
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

2361337E



34.845558,
-116.778168


2361336E



2361335E



2361334E



2361333E



2361332E



2361331E



2361330E



4792303E



4792302E



34.84426,
-116.76993



Figure 9, Page 12 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Ditch/Canal
-  Ditch/Canal - Bank



Figure 9, Page 13 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Ditch/Canal
-  Ditch/Canal - Bank

2361367E



34.843038,
-116.760007

2361366E



2361365E



2361364E



2361363E



2361362E



2361361E



2361360E



2361358E



2361357E



34.84182,
-116.752186



Figure 9, Page 14 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Ditch/Canal
-  Ditch/Canal - Bank
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 15 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Ditch/Canal
-  Ditch/Canal - Bank



Figure 9, Page 16 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV TRANSMISSION LINE REMEDIAL ACTION SCHEME PROJECT
 AQUATIC RESOURCES DELINEATION





- Survey Area
- CDFW Aquatic Resources**
- Ditch/Canal
- Ditch/Canal - Bank
- Streambed Unvegetated
- Streambed Unvegetated - Bank



Figure 9, Page 17 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Ditch/Canal
-  Ditch/Canal - Bank
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 18 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- CDFW Aquatic Resources**
- Ditch/Canal
- Ditch/Canal - Bank
- Streambed Unvegetated
- Streambed Unvegetated - Bank

2847464E



34.836281,
-116.716401

2847463E



2847462E



2847461E



2847460E



2847459E



2847458E



2847457E



2847456E



2847455E



34.835034,
-116.708347



Figure 9, Page 19 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Ditch/Canal
-  Ditch/Canal - Bank
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

2347454E



34.834896,
-116.707462

2347453E



2344309E,
2347452E



2347451E,
2347550E



2347548E,
2347549E



2347545E,
2347546E



2344308E,
2347545E



2347544E



2347543E



2347542E



34.832628,
-116.699783



Figure 9, Page 20 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Ditch/Canal - Bank
- Streambed Unvegetated
- Streambed Unvegetated - Bank



Figure 9, Page 21 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





 Survey Area



Figure 9, Page 22 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





 Survey Area



Figure 9, Page 23 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





○ Survey Area



Figure 9, Page 24 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





○ Survey Area



Figure 9, Page 25 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank



Figure 9, Page 26 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV TRANSMISSION LINE REMEDIAL ACTION SCHEME PROJECT
 AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 27 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 28 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 29 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- CDFW Aquatic Resources**
- Ditch/Canal
- Streambed Unvegetated
- Streambed Unvegetated - Bank



Figure 9, Page 30 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Ditch/Canal
- Ditch/Canal - Bank




Figure 9, Page 31 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Ditch/Canal



Figure 9, Page 32 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





Survey Area



Figure 9, Page 33 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV TRANSMISSION LINE REMEDIAL ACTION SCHEME PROJECT
 AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Playa



Figure 9, Page 34 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Playa



Figure 9, Page 35 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Playa



Figure 9, Page 36 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV TRANSMISSION LINE REMEDIAL ACTION SCHEME PROJECT
 AQUATIC RESOURCES DELINEATION





- Survey Area
- CDFW Aquatic Resources**
- Playa
- Streambed Unvegetated
- Streambed Unvegetated - Bank

34.805896,
-116.568027

34.804412,
-116.559762



Figure 9, Page 37 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Playa



Figure 9, Page 38 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





 Survey Area
CDFW Aquatic Resources
 Playa




Figure 9, Page 39 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Playa



Figure 9, Page 40 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 41 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION






- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank



Figure 9, Page 42 of 189
**CDFW Aquatic Resources
 Survey Results**
 LUGO-VICTORVILLE 500-KV
 TRANSMISSION LINE REMEDIAL
 ACTION SCHEME PROJECT
 AQUATIC RESOURCES DELINEATION





- Survey Area
- CDFW Aquatic Resources**
- Playa
- Streambed Unvegetated
- Streambed Unvegetated - Bank




Figure 9, Page 43 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 44 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank




Figure 9, Page 45 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 46 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank




Figure 9, Page 47 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank



Figure 9, Page 48 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank



Figure 9, Page 49 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Basin
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank



Figure 9, Page 50 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV TRANSMISSION LINE REMEDIAL ACTION SCHEME PROJECT
 AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Basin
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank



Figure 9, Page 51 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank



Figure 9, Page 52 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank



Figure 9, Page 53 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- CDFW Aquatic Resources**
- Basin
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank




Figure 9, Page 54 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank

1700530E
 34.781495,
 -116.409903

1700579E
 21
 22 23

1700578E

1700577E

1700576E

1700575E
 34.779813,
 -116.402635





Figure 9, Page 55 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
 TRANSMISSION LINE REMEDIAL
 ACTION SCHEME PROJECT
 AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank




Figure 9, Page 56 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank




Figure 9, Page 57 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank




Figure 9, Page 58 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV TRANSMISSION LINE REMEDIAL ACTION SCHEME PROJECT
 AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank

34.792845,
-116.37267

M63-T5

34.788857,
-116.377904

M63-T4




Figure 9, Page 59 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank



Figure 9, Page 60 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank

34.804581,
-116.358464

M70-T2

M70-T1

M69-T6

34.799952,
-116.364723

M69-T3



Figure 9, Page 61 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION



-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank







Figure 9, Page 62 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank

34.815425,
-116.345594

M71-T1

M70-T6

34.811391,
-116.351172




Figure 9, Page 63 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 64 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank



Figure 9, Page 65 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank



Figure 9, Page 66 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV TRANSMISSION LINE REMEDIAL ACTION SCHEME PROJECT
 AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank




Figure 9, Page 67 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank

M74-T3
34.845321,
-116.300153

M74-T2

M74-T1

34.841151,
-116.306432



Figure 9, Page 68 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





34.847712,
-116.294997

M75-T3
34.852396,
-116.287652

-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank



Figure 9, Page 69 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank



Figure 9, Page 70 of 189

CDFW Aquatic Resources Survey Results


LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION



34.853296,
-116.285129

-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank

34.862849,
-116.269173




M76-T4

M76-T3



M76-T2



34.85883,
-116.275346



Figure 9, Page 71 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank



Figure 9, Page 72 of 189

**CDFW Aquatic Resources
Survey Results**

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





- Survey Area
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank



Figure 9, Page 73 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank



Figure 9, Page 74 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV TRANSMISSION LINE REMEDIAL ACTION SCHEME PROJECT
 AQUATIC RESOURCES DELINEATION





- Survey Area
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank



Figure 9, Page 75 of 189

CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV
TRANSMISSION LINE REMEDIAL
ACTION SCHEME PROJECT
AQUATIC RESOURCES DELINEATION

