



- Survey Area
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank



Figure 9, Page 76 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION



M79-T3  
34.88742,  
-116.228252

M80-T1  
34.891755,  
-116.220853

M79-T4

M79-T5



-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank

34.895731,  
-116.211179

M80-T4

M80-T3

M80-T2

34.891882,  
-116.219356



Figure 9, Page 77 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank



Figure 9, Page 78 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank

34.906598,  
-116.202108

34.91085,  
-116.197464

M81-T5

43

M81-T6

M81-T4



Figure 9, Page 79 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank



Figure 9, Page 80 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank




Figure 9, Page 81 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV TRANSMISSION LINE REMEDIAL ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank

M83-T4  
 34.928359,  
 -116.18121

M83-T3

M83-T2  
 34.924677,  
 -116.18535




Figure 9, Page 82 of 189

**CDFW Aquatic Resources  
 Survey Results**

LUGO-VICTORVILLE 500-KV  
 TRANSMISSION LINE REMEDIAL  
 ACTION SCHEME PROJECT  
 AQUATIC RESOURCES DELINEATION





- Survey Area
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank

34.934203,  
-116.175792

M83-T6

M83-T5

34.929912,  
-116.180487




Figure 9, Page 83 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank



Figure 9, Page 84 of 189

**CDFW Aquatic Resources  
Survey Results**


LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank

M35-T1 34.9455,  
-116.163107



M34-T5

34.941513,  
-116.168493





Figure 9, Page 85 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank



Figure 9, Page 86 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION



34.946748,  
-116.161422

34.951306,  
-116.154413



-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank




Figure 9, Page 87 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





- Survey Area
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank

34.963347,  
-116.138157

M36-T7

M36-T6

M36-T5

M36-T4

34.958769,  
-116.145166




Figure 9, Page 88 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





- Survey Area
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank

34.969451,  
-116.129904

M87-T4

M87-T3

M87-T2

M87-T1

34.964827,  
-116.136979




Figure 9, Page 89 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank



Figure 9, Page 90 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 91 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

34.987261,  
-116.10582

M89-T3

M89-T2

M89-T1

M89-T6

34.982547,  
-116.11302




Figure 9, Page 92 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





- Survey Area
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated - Bank



Figure 9, Page 93 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV TRANSMISSION LINE REMEDIAL ACTION SCHEME PROJECT  
 AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 94 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 95 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank



Figure 9, Page 96 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV TRANSMISSION LINE REMEDIAL ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank





Figure 9, Page 97 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank

35.022272,  
-116.043717

M93-T5

M93-T4

M93-T3

M93-T2

35.018149,  
-116.051044



Figure 9, Page 98 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated - Bank

M94-T2 35.026327,  
-116.035574

M94-T1

M93-T7

M93-T6


35.02276,  
-116.041946



Figure 9, Page 99 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





 Survey Area

M94-T5 35.030209,  
-116.027598

M94-T4

M94-T3

35.026744,  
-116.033654



Figure 9, Page 100 of 189

**CDFW Aquatic Resources Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 101 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Vegetated
-  Streambed Vegetated - Bank



Figure 9, Page 102 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 103 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Vegetated
-  Streambed Vegetated - Bank

M96-T5  
 35.035503,  
 -115.99187

M97-T2

35.03708,  
 -115.983976  
 M97-T3




Figure 9, Page 104 of 189

**CDFW Aquatic Resources  
 Survey Results**

LUGO-VICTORVILLE 500-KV  
 TRANSMISSION LINE REMEDIAL  
 ACTION SCHEME PROJECT  
 AQUATIC RESOURCES DELINEATION





 Survey Area



Figure 9, Page 105 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 106 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

35.04002,  
-115.960361

M93-T3

M93-T4

35.041119,  
-115.955928



Figure 9, Page 107 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





35.042264,  
-115.951069

M99-T1

M99-T2

35.044208,  
-115.946606

 Survey Area



Figure 9, Page 108 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





○ Survey Area



Figure 9, Page 109 of 189

**CDFW Aquatic Resources Survey Results**

LUGO-VICTORVILLE 500-KV TRANSMISSION LINE REMEDIAL ACTION SCHEME PROJECT  
 AQUATIC RESOURCES DELINEATION





○ Survey Area

M100-T2  
 35.048736,  
 -115.932137

M100-T3

M100-T4  
 35.051968,  
 -115.925448




Figure 9, Page 110 of 189

**CDFW Aquatic Resources  
 Survey Results**

LUGO-VICTORVILLE 500-KV  
 TRANSMISSION LINE REMEDIAL  
 ACTION SCHEME PROJECT  
 AQUATIC RESOURCES DELINEATION



○ Survey Area



35.0563,  
M101-T3 -115.914823

M101-T2

M101-T1

M100-T5

35.052572,  
-115.922735




Figure 9, Page 111 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





 Survey Area




Figure 9, Page 112 of 189

**CDFW Aquatic Resources Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





○ Survey Area

35.063807,  
-115.89621

M102-T5

M102-T4

M102-T3

M102-T2

35.060168,  
-115.9041



Figure 9, Page 113 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





 Survey Area

M103-T2 35.067977,  
-115.886144

M103-T1

M102-T6

35.064474,  
-115.893555



Figure 9, Page 114 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





 Survey Area



Figure 9, Page 115 of 189

**CDFW Aquatic Resources Survey Results**

LUGO-VICTORVILLE 500-KV TRANSMISSION LINE REMEDIAL ACTION SCHEME PROJECT  
 AQUATIC RESOURCES DELINEATION





- Survey Area
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank

35.073232,  
-115.872225

M104-T1

M104-T2

M104-T3  
35.07525,  
-115.865474



Figure 9, Page 116 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated

35.076036,  
-115.862195

M105-T1  
35.078475,  
-115.854666

M104-T5

M104-T4



Figure 9, Page 117 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank

35.079536,  
-115.853209

35.082087,  
-115.847922



Figure 9, Page 118 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank



Figure 9, Page 119 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 120 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank




Figure 9, Page 121 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank

M103-T1  
 35.105331,  
 -115.815496

M107-T4

M107-T3

35.100995,  
 -115.82236




Figure 9, Page 122 of 189

**CDFW Aquatic Resources  
 Survey Results**

LUGO-VICTORVILLE 500-KV  
 TRANSMISSION LINE REMEDIAL  
 ACTION SCHEME PROJECT  
 AQUATIC RESOURCES DELINEATION





- Survey Area
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank
- Streambed Vegetated
- Streambed Vegetated - Bank

M109-T1  
35.112379,  
-115.802793

M103-T5

M103-T4

M103-T3

35.108065,  
-115.809616



Figure 9, Page 123 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 124 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION



35.113227,  
-115.800226

M109-T5 35.117578,  
-115.793099

M109-T4

M109-T3

M109-T2



-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 125 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank

M110-T5  
35.126534,  
-115.775843

M110-T4

M110-T3

35.123043,  
-115.781554



Figure 9, Page 126 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank

35.131966,  
-115.765383

M111-T4

M111-T3

M111-T2

M111-T1

35.12744,  
-115.773103



Figure 9, Page 127 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 128 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 129 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 130 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION






-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 131 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

M114-T4 35.157563,  
-115.716059

M114-T3

M114-T2

35.153302,  
-115.723279




Figure 9, Page 132 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

M115-T4 35.164604,  
-115.702477

M115-T3

M115-T2

35.16045,  
-115.709496



Figure 9, Page 133 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

M116-T2  
35.169625,  
-115.69279

M116-T1

M116-T5

35.165695,  
-115.69938



Figure 9, Page 134 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 135 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Ditch/Canal
-  Ditch/Canal - Bank
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank

M117-T3 35.179484, -115.673761

M117-T2

M117-T1

35.175298, -115.680851




Figure 9, Page 136 of 189

**CDFW Aquatic Resources Survey Results**

LUGO-VICTORVILLE 500-KV TRANSMISSION LINE REMEDIAL ACTION SCHEME PROJECT  
 AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 137 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

M118-T5 35.188518,  
-115.654994

M118-T4

M118-T3

35.184575,  
-115.662387



Figure 9, Page 138 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

M119-T3 35.193429,  
-115.644446

M119-T2

M119-T1

35.189655,  
-115.651475





Figure 9, Page 139 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

M120-T2 35.198205,  
-115.634184

M120-T1

M119-T4

35.19433,  
-115.64143




Figure 9, Page 140 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 141 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank





Figure 9, Page 142 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 143 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank



Figure 9, Page 144 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank

M123-T4 35.223771,  
-115.579186

M123-T3

M123-T2

35.220154,  
-115.585887



Figure 9, Page 145 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank



Figure 9, Page 146 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 147 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION



-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 148 of 189

**CDFW Aquatic Resources Survey Results**

LUGO-VICTORVILLE 500-KV TRANSMISSION LINE REMEDIAL ACTION SCHEME PROJECT  
 AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 149 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

M126-T5 35.24533,  
-115.532743

M126-T4

M126-T3

35.242137,  
-115.538543




Figure 9, Page 150 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 151 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Ditch/Canal
-  Ditch/Canal - Bank
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 152 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV TRANSMISSION LINE REMEDIAL ACTION SCHEME PROJECT  
 AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Ditch/Canal
-  Ditch/Canal - Bank
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 153 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





M129-T1 35.262943, -115.497784

M123-T5

M123-T4

35.25818, -115.50395

-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 154 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 155 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 156 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

35.279473,  
-115.474456

M130-T4

M130-T3

35.276731,  
-115.478431



Figure 9, Page 157 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





- Survey Area
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank



Figure 9, Page 158 of 189

### CDFW Aquatic Resources Survey Results



LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION



35.284355,  
-115.467887



35.289275,  
-115.46014



M131-T3

M131-T4

M131-T2



35.291785,  
-115.457484

M1E2-T1

M1E2-T2

35.294305,  
-115.453151

-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 159 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 160 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank



Figure 9, Page 161 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 162 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

35.32021,  
-115.417135

M135-T1

M134-T4

M134-T3

35.315383,  
-115.424681




Figure 9, Page 163 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

35.327228,  
-115.407372

M185-T4

M185-T3

35.322536,  
-115.414731

M185-T2



Figure 9, Page 164 of 189


**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION




-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

M186-T2 35.332731,  
-115.400581



M186-T1



35.329406,  
-115.404379



Figure 9, Page 165 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION



-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank





Figure 9, Page 166 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION



-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

M187-12 35.342826,  
-115.386528



M187-11

35.339548,  
-115.390262




Figure 9, Page 167 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





- Survey Area
- Photo Location
- CDFW Aquatic Resources**
- Streambed Unvegetated
- Streambed Unvegetated - Bank




Figure 9, Page 168 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 169 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION



-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

M189-T3 35.364191,  
-115.356771



M189-T2

35.360777,  
-115.360701




Figure 9, Page 170 of 189


### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION




-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

M140-T2 35.369755,  
-115.349016



M140-T1



35.366297,  
-115.353006



Figure 9, Page 171 of 189


**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION



-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

M140-T4 35.37523,  
-115.341385



M140-T3



35.371862,  
-115.345249



Figure 9, Page 172 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV TRANSMISSION LINE REMEDIAL ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 173 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION






-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 174 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION



-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 175 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION



-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 176 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION



-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 177 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION



-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 178 of 189


**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION




-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank

M145-T1 35.41553,  
-115.285158



M144-T3



35.412137,  
-115.289063




Figure 9, Page 179 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION






-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 180 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION



-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank



Figure 9, Page 181 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION



-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



M146-T3  
35.431535,  
-115.262801

M146-T2

35.428234,  
-115.266583



Figure 9, Page 182 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank



Figure 9, Page 183 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION





-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank




Figure 9, Page 184 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION



-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank





Figure 9, Page 185 of 189


**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION



-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank

M149-T1 35.452549,  
-115.233424



M143-T3

35.449142,  
-115.237358




Figure 9, Page 186 of 189

**CDFW Aquatic Resources  
Survey Results**

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION



-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank






Figure 9, Page 187 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION



-  Survey Area
- CDFW Aquatic Resources**
-  Streambed Unvegetated
-  Streambed Unvegetated - Bank
-  Streambed Vegetated
-  Streambed Vegetated - Bank



35.460325,  
-115.222514

35.463115,  
-115.217434




Figure 9, Page 188 of 189

### CDFW Aquatic Resources Survey Results

LUGO-VICTORVILLE 500-KV  
TRANSMISSION LINE REMEDIAL  
ACTION SCHEME PROJECT  
AQUATIC RESOURCES DELINEATION

