



- Barrier Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed

Before Photo  
Not Available

**Before**



After Photo  
Not Available

**Site Name:** A-6 Road

**Stream Name:** Glenbrook Gulch

**Structure Owner:** State Parks

**Year Remediated:** 2011

**Site Type:** Road crossing

**Site Status After Remediation:** Not a barrier

**Species Benefited After Remediation:**

**Immediate Downstream barrier PAD ID:**

**PAD ID:** 730616

**Tributary To:** Albion River

**Barrier Remediation By:** State Parks

**Barrier Description Prior to Remediation:** Total

**Count of Barriers Downstream:**

**Count of Barriers Upstream:** 0

**Distance Upstream to Next Barrier or Limit of Anadromy :** 1.6 Miles

\*Site statistics based on June 2015 version of the Passage Assessment Database

**Notes:** Glenbrook Gulch Anadromous Fish Habitat Restoration Project. Per CDFW, this was a total barrier. After treatment, 1 redd and an abundance of juvenile coho were observed upstream in a 2013 spawner survey. Funded by CDFW FRGP. Before: "Unknown" passage status.