


- Barrier Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed



Photo Credit: Mendocino County RCD



After Photo
Not Available

Site Name: removed culvert and rerouted channel

Stream Name:

Structure Owner:

Year Remediated: 2011

Site Type: Road crossing

Site Status After Remediation: Remediated, fish response unconfirmed

Species Benefited After Remediation:

Immediate Downstream barrier PAD ID:

PAD ID: 737273

Tributary To: Dunn Creek

Barrier Remediation By: Unknown

Barrier Description Prior to Remediation: Temporal & Partial

Count of Barriers Downstream:

Count of Barriers Upstream:

Distance Upstream to Next Barrier or Limit of Anadromy : Miles

*Site statistics based on June 2015 version of the Passage Assessment Database

Notes: Removed in 2011; rerouted channel and created low-gradient backwater habitat. BEFORE: 3-foot culvert, barrier to adult and juvenile salmonids, 36 inch CMP Culvert. Was a 'temporal & partial' barrier.