



- Barriers Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed



Site Name: concrete sill
Stream Name: Bridge Creek
Structure Owner:
Year Remediated: 2011
Site Type: Other
Site Status After Remediation: Not a barrier
Species Benefited After Remediation: coho
Immediate Downstream barrier PAD ID:

PAD ID: 758267
Tributary To: South Fork Eel River
Barrier Remediation By: Unknown
Barrier Description Prior to Remediation: Partial
Count of Barriers Downstream:
Count of Barriers Upstream:
Distance Upstream to Next Barrier or Limit of Anadromy : Miles

*Site statistics based on June 2015 version of the Passage Assessment Database

Notes: A concrete sill was removed to improve passage to juvenile and adult salmonids. It was a partial barrier. Coho, specifically YOY, were seen on Bridge creek for the first time during a snorkel survey on 9/13/2012 after this barrier was removed. Survey field note recommends improving instream shelter using available wood lying on riparian banks, and removing concrete and metal pieces from a house that washed away.