


- Barrier Remediated in 2011
- Section Opened to Fish Passage
- ⋯ Section Above Partial Barrier
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed

Before Photo  
Not Available



After Photo  
Not Available

**Site Name:** Low flow Arizona Crossing (ford, T8) on Tajiguas Creek

**Stream Name:** Tajiguas Creek

**Structure Owner:** Not available

**Year Removed:** 2011

**Barrier Description Prior to Removal:** Low flow Arizona crossing

**Site Description After Removal:** Natural streambed rebuilt

**Site Status After Removal:** Remediated, fish response unconfirmed

**Count of Total Barriers Downstream:** 1

**Count of Barriers with Unknown Passage Status Downstream:** 2

**Distance to Next Barrier Upstream with Barrier Status and PAD ID:** 0.11 miles, Unknown barrier, [706360](#)

**Distance to Next Total Barrier Upstream with PAD ID:** 0.26 miles, [706363](#)

**PAD ID:** [758547](#)

**Tributary To:** Pacific

**Barrier Removed By:** Not available

**Barrier Status Prior to Removal:** Not available

**Species Benefited After Removal:** Not available

**Count of Partial Barriers Downstream:** 0

**Count of Unscreened Diversions Downstream:** 0

**Distance to End of Natural Anadromy:** Unknown

\*Site statistics based on February 2013 version of the Passage Assessment Database