

UPPER TWIN LAKE

EL DORADO CO.

July 26, 1949

Does not appear as if additional storage can be had here except at considerable additional cost.- low damsite-dam has 10" control valve pipe about 2 ft. depth. Ed Smith OK's any feasible height (cost factor. Outlet temp. 61° 11:50 A.M. Note that spawning beds could be created below outlet by putting gravels in. There are impassable falls just above inlet. Above falls (below Mirror pond) there are numerous small EB)

JCF