


- Barrier Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed

Before Photo  
Not Available



**Site Name:** Joe Sanchez Farms  
**Stream Name:** Steamboat Slough  
**Structure Owner:** Private landowner(s) (non-corporate)  
**Year Remediated:** 2013  
**Site Type:** Diversion  
**Site Status After Remediation:** Screened  
**Species Benefited After Remediation:** Chinook salmon  
**Immediate Downstream barrier PAD ID:**  
**Notes:** Screened to 24 cfs by FWA in May 2013.

**PAD ID:** 700640  
**Tributary To:** Cache Slough  
**Barrier Remediation By:** Family Water Alliance  
**Barrier Description Prior to Remediation:** Unscreened  
**Count of Barriers Downstream:**  
**Count of Barriers Upstream:**  
**Distance Upstream to Next Barrier or Limit of Anadromy :**                      mi

\*Site statistics based on December 2014 version of the Passage Assessment Database