



After Photo  
Not Available

**Site Name:** PORTUGUESE BEND PUMP PLANT SMWC

**Stream Name:** Sacramento River

**Structure Owner:** Sutter Mutual Water Co. / Frank Lamb Trust

**Year Screened:** 2011

**Barrier Description Prior to Screening:** Unscreened diversion

**Site Description After Screening:** Screened diversion

**Site Status After Screening:** Screened, fish response unconfirmed

**Count of Total Barriers Downstream:** 0

**Count of Barriers with Unknown Passage Status Downstream:** 9

**Distance to Next Barrier Upstream with Barrier Status and PAD ID:** 0.04 miles, Unscreened diversion, [700855](#)

**Distance to Next Total Barrier Upstream with PAD ID:** 129 miles, [718715](#)

**PAD ID:** [700856](#)

**Tributary To:** San Francisco Bay

**Diversion Screened By:** Not available

**Barrier Status Prior to Screening:** Unscreened diversion

**Species Benefited After Screening:** Not available

**Count of Partial Barriers Downstream:** 0

**Count of Unscreened Diversions Downstream:** 412

**Distance to End of Natural Anadromy:** Unknown

\*Site statistics based on February 2013 version of the Passage Assessment Database