



After Photo
Not Available

Site Name: Budiselich Dam

Stream Name: Mormon Slough

Structure Owner: Stockton East Water District

Year Removed: 2011

Barrier Description Prior to Removal: 8 to 12 foot concrete barrier

Site Description After Removal: 7 v-shaped boulder weirs installed creating ramp/channel

Site Status After Removal: Remediated, fish response unconfirmed

Count of Total Barriers Downstream: 0

Count of Barriers with Unknown Passage Status Downstream: 0

Distance to Next Barrier Upstream with Barrier Status and PAD ID: 0.16 miles, Unscreened diversion, [704058](#)

Distance to Next Total Barrier Upstream with PAD ID: 4.84 miles, [735110](#)

PAD ID: [735107](#)

Tributary To: Calaveras River

Barrier Removed By: Not available

Barrier Status Prior to Removal: Temporal

Species Benefited After Removal: Not available

Count of Partial Barriers Downstream: 3

Count of Unscreened Diversions Downstream: 118

Distance to End of Natural Anadromy: Unknown

*Site statistics based on February 2013 version of the Passage Assessment Database