


- Barrier Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed

Before Photo
Not Available



After Photo
Not Available

Site Name: NATOMAS NORTH MAIN PUMPING STATION

Stream Name: Cross Canal

Structure Owner: Natomas Central Mutual Water Co.

Year Remediated: 2012

Site Type: Diversion

Site Status After Remediation: Not a barrier

Species Benefited After Remediation: Unknown

Immediate Downstream barrier PAD ID:

PAD ID: [702857](#)

Tributary To: Sacramento River

Barrier Remediation By: U.S. Fish and Wildlife Service

Barrier Description Prior to Remediation: Unscreened

Count of Barriers Downstream:

Count of Barriers Upstream:

Distance Upstream to Next Barrier or Limit of Anadromy : mi

*Site statistics based on December 2014 version of the Passage Assessment Database

Notes: This was an unscreened diversion per a field survey in 1994 assessed by CDFW. In November 2012, the Bolen, Northern, and Bennett diversions on the Natomas Cross Canal was removed and replaced with a consolidated screened diversion on the Sacramento River at Sankey (PAD ID 758606). At the same time the diversion structure at this location was removed except for the concrete foundations which were left in place to avoid adverse habitat impacts.