

July 27, 1959

Warden E. A. Johnson

Terence Potter

Highland Lake Check Dam

One of our seasonal aids and I were in to Highland Lake July 23, 1959. At that time, there were only about $2\frac{1}{2}$ ' of storage left and a flow of 2.75 c.f.s. through the valve.

We found two sticks about 4" long and $1\frac{1}{2}$ " in diameter wedged behind the gate. We removed the sticks and the valve works o.k.

I left the valve open to allow .25 c.f.s. flow which is about the best that can be done. I took out the weir board and left it under the dead log near the weir. We cleaned all the sticks out of the wall. I see no use of anyone making any more trips this year to regulate the valve. Next summer the flow can be adjusted to the desired flow.

Hope your wheel fit all right at Barrett Lake.

Terence Potter
Fisheries Manager I
Region II

TP/rs

cc: Captain Whitesell