

Memorandum

To : Survey Files

Date: January 25, 1978

From : **Department of Fish and Game**

Subject: Highland Lake, El Dorado Co.

Highland Lake Dam was breached at a point approximately 40 feet south of the northern end of the dam. The dam was breached in order to remove it from the State Division of Dam Safety jurisdiction and thus avoid costly repairs. The hole torn out was approximately 14 inches deep by 15 inches long, and the rocks and mortar about 10 inches in depth before it was realized that the lower layer of the structure there was solid. This site was abandoned and efforts moved to the previously mentioned location.



Scott Collier
Seasonal Aid
Region 2

SC:sw