


- ★ Diversion Screened in 2011
- Section Opened to Fish Passage
- ⋯ Section Above Partial Barrier
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed



Before Photo
Not Available

After Photo
Not Available

Site Name: SOUTH STEINER BEND PLANT RD108

Stream Name: Sacramento River

Structure Owner: Reclamation District 108

Year Screened: 2011

Barrier Description Prior to Screening: Unscreened diversion

Site Description After Screening: Screened diversion

Site Status After Screening: Screened, fish response unconfirmed

Count of Total Barriers Downstream: 0

Count of Barriers with Unknown Passage Status Downstream: 12

Distance to Next Barrier Upstream with Barrier Status and PAD ID: 0.55 miles, Unscreened diversion, [703558](#)

Distance to Next Total Barrier Upstream with PAD ID: 102 miles, [718715](#)

PAD ID: [703600](#)

Tributary To: San Francisco Bay

Diversion Screened By: Not available

Barrier Status Prior to Screening: Unscreened diversion

Species Benefited After Screening: Not available

Count of Partial Barriers Downstream: 0

Count of Unscreened Diversions Downstream: 462

Distance to End of Natural Anadromy: Unknown

*Site statistics based on February 2013 version of the Passage Assessment Database