

Taylor Creek

April 30, 1942

W41^o 10 am. 8 18-24 in. trout between
Highway Bridge and our dam. None seen in
 $\frac{1}{4}$ mile above our dam. Trestle to PH
not over 1500 feet.

Curtis

NIGHT LETTER

12/3/54 - 4:05 p.m.

*Taylor Creek
El Dorado Co.*

VAUGHN HOFELDT
MEYERS RANGER STATION
MEYERS, CALIFORNIA

FIELD MEN REPORT LOW FLOW TAYLOR CREEK YESTERDAY. NO KOKANEE RUN EVIDENT.

IS THERE ANY POSSIBILITY OF RELEASING MORE WATER FROM FALLEN LEAF.

D. W. KELLEY

Phoned: jp

1) Est. Flow = 250-300 c.f.s.

2) Water slightly Turbid.

3) No fish seen.

4) Old Tallac dam completely submerged by water flow - would present no problem a barrier now - would during low flow

5) Fallen Tree, with debris fill behind would probably act as partial barrier during low flows - photo Taber (#1) located above old dam -

Just about 50 yards below stream fork.

6) Water temp. = 47°F @ 12:30P

7) Several logs across stream at various locations, however none of them constitute barrier

8) River between hwy & mouth - no barriers - although river at present is spread out over meadow. Mouth open now.

60968 3-52 17,500 SPO

Date May 25 1955

Locality

Taylor Creek

Subject

(over)

stream visited earlier - low
flow (at C.C.F.S.) - Saw 6 RITs
in pool below Hwy 89 bridge.
old log jam about $\frac{1}{2}$ way
between bridge + mouth - may
need work.

During high flow. saw
evidence of new debris
barrier about 200 yds.
below hwy bridge.
High water in meadow made
close observation difficult

Taylor Creek

Subject

Date

Nov 4, 1955

Locality

Lake Tahoe to Fallen Leaf

60968 3-52 17,500 SPO

Flow 5 cfs. (est.)

6 log jams above 89 bridge, 3 defunct
impassible at 5 ^{+ current water flows} ~~log jams below bridge~~

Westgate

Notes made by

Kohance Taylor Creek

Subject

Date Nov 21, 1955 Locality Tahoe to 89 bridge

60968 3-52 17,500 SPO

Bob Ross (sportsman)

Temp. water 39°F Flow est 7 cfs.

Kohance appear to pass ~~over~~ device at mouth (about 8 seen just below, but many above).

Approx 7 pas seen from lake to 89 bridge, also 4 single ^{KOK} males, several browns. Log jam apparent was not passable. Cleared partly and 4 KOK immediately passed upstream. On return to mouth, about 15 KOK seen in one hole. No spawning seen.

Notes made by

Bross reports last year he
saw no BOK above 89 bridge.
Last Sat., Bross and Rev. F+G
saw many BOK in lower
pools, but none up as
far as today.

Kohonee Spawning Taylor Cr.

Subject

Date

Dec 5, 1956

Locality

Tahoe to hatchery dam

60968 3-52 17,500 SPO

110 Koh seen from lake to 89 bridge
12 from 89 bridge to old dam. Poor visibility.
None seen above 100 yds from 89 bridge,
but no obvious barrier until dam.

No redds recognized. 1 dead male
and 1 gaffed(?) female not spawned.

Est. there were 200-300 Kohonee in creek.

Est. flow 7-10 cfs.

Notes made by