

FILE NOTE

TRUCKEE RIVER, UPPER, El Dorado County

8/25/54

Flow about 1-2 c.f.s. below diversions. About 4 c.f.s. above top dam. Woodhull and I walked section from Mable Scott's first (top) diversion dam. Erosion begins about here and gets progressively worse as you go downstream. Mable Scott property is not so badly overgrazed as Broders or Lake Valley Development Co, or Kyburz. There are areas of decomposed granite where fencing would probably do little good but on the other hand I feel sure that we could improve some of the riffle areas by washing the silt out of the gravel.

Woodhull suggests Deniel ladder over Scott dam.

D. W. Kelley  
Associate Fisheries Biologist  
Region II