


Refugio Oil Spill - SCAT Segment Status
As of Most Recent Survey
Most Recent Survey Data: 6/08/2015



Status	Total Miles = 96.5
% Active	25%
% Complete	75%

Segment Status

- Active
- Met Cleanup Goals
- Met Cleanup Goals (w/ Continued Monitoring)
- Met Cleanup Goals (w/ Continued Sampling)

Note: Divisions are made up of individual segments. N

The information presented here is primarily for informational purposes, and is based on the most available SCAT data at the time of publication. Equipment in SCAT that does not have a tag, or data in the SCAT that does not have a tag, is not included in this report. The information presented here may be subject to change as more data is received.