



# Refugio Response Joint Information Center

DATE: June 24, 2015 11:48:43 AM PDT

## Before and After Images for Refugio Oil Spill Response

### Restoration of Pipeline Excavation Site, SSE View



Left: May 25, 2015.

Right: June 3, 2015.

### Restoration of Pipeline Excavation Site, ENE View



Left: May 24, 2015.

Right: June 3, 2015.

### Restoration of Pipeline Excavation Site, NNE View



Left: May 24, 2015.

Right: June 3, 2015.

---

## Refugio State Beach During Cleanup




Left: May 29, 2015.

Right: June 3, 2015.

---

## Kelp at Refugio State Beach During Cleanup



Left: May 22, 2015.

Right: June 3, 2015.

---

## Cleanup teams between Refugio and El Capitan State Beach



Left: May 29, 2015.

Right: June 3, 2015.



---

## Refugio State Beach During Cleanup



Left: May 29, 2015.

Right: June 3, 2015.

---

## Bluff at Refugio State Beach During Cleanup, Pending Restoration



Left: June 2, 2015.

Right: June 17, 2015.

---

## Bluff at Refugio State Beach During Cleanup, Pending Restoration



Left: June 2, 2015.

Right: June 17, 2015.

---

## Drainage Culvert North of HWY 101



Left: May 21, 2015.

Right: June 23, 2015.