



Refugio Response Joint Information Center

FOR IMMEDIATE RELEASE

DATE: May 21, 2015 10:23:08 PM PDT

Refugio Oil Spill Clean Up Operations (photos and video)



Response crews collect oil from on the water as well as clean beaches impacted by an oil spill along the coast north of Santa Barbara, Calif., May 21, 2015. Oil, which spilled from an on-land pipeline several miles of coastline as crews battle to clean up and reduce the impact of the spilled oil. U.S. Coast Guard photo by Chief Petty Officer David Mosley.



Members of wildlife response organizations walk past an oil covered rock as they look for wildlife impacted by an oil spill along the beach near El Capitan State Beach, Calif., May 21, 2015. Oil, which spilled from an on-land pipeline, impacted several miles of coast line as crews battle to clean up and reduce the impact of the spilled oil. (U.S. Coast Guard photo by Chief Petty Officer David Mosley.)



Beach cleanup crew members pick up oiled seaweed and ocean debris from the beach near Refugio State Beach, Calif., May 21, 2015. Clean up teams are worked along several miles of beach north of Santa Barbara to clean and minimize impact to the maritime environment. (U.S. Coast Guard photo by Chief Petty Officer David Mosley.)



Beach cleanup crew members use a shovel to place gathered oil and affected sand into a bag as they clean up along a beach near Refugio State Beach, Calif., May 21, 2015. Clean up teams used shovels and their hands to gather affected soil and ocean debris along oil impacted beaches north of Santa Barbara. (U.S. Coast Guard photo by Chief Petty Officer David Mosley.)

For more information contact:

Joint Information Center
(805) 770-3682
www.refugioresponse.com