


- Barrier Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed



After Photo
Not Available

Site Name: Arnold Drive Private (Stuart Creek Run Barrier)

Stream Name: Stuart Creek

Structure Owner:

Year Remediated: 2014

Site Type: Road crossing

Site Status After Remediation: Remediated, fish response unconfirmed

Species Benefited After Remediation:

Immediate Downstream barrier PAD ID: 712578

PAD ID: 712577

Tributary To: Calabazas Creek

Barrier Remediation By: Sonoma Land Trust

Barrier Description Prior to Remediation: Partial

Count of Barriers Downstream: 3

Count of Barriers Upstream: 4

Distance Upstream to Next Barrier or Limit of Anadromy : 1.01763 Miles

*Site statistics based on June 2015 version of the Passage Assessment Database

Notes: In 2014, a concrete bridge foundation was removed and a chute-pool channel was constructed. Before: Partial barrier per DFG Restoration Manual per Sonoma Ecology Center. One culvert RED filter result, second culvert GREY filter result. Eroding bridge on Sonoma Creek.