



Region 2 Barrier ID: W096 (Barrier).

Barrier Name: Cohasset Rd.

Linear Infrastructure: County Road.

Geographic Area: Butte County, Cohasset Road Northeast of Chico.

Length: 5.37 km (3.34 mi).

Target Species: Deer (*Odocoileus hemionus*), mountain lion (*Puma concolor*), black bear (*Ursus americanus*).

Connectivity Concerns: This stretch of Cohasset Road leads out of town and is a noted spot for animal vehicle collision. Migratory deer from the Bucks Mountain/Mooretown deer herd winter here along with resident deer and make daily and seasonal movements across Cohasset Road.

Remediation Goals: Expand and enhance existing infrastructure such as culverts and creek bridges, add new wildlife crossing structures and wildlife exclusion fencing.




Figure: Cohasset Road is a Region 2 wildlife connectivity barrier.