



Region 2 Barrier ID: W098 (Barrier).

Barrier Name: SR-162 Canyon Creek.

Linear Infrastructure: SR-162.

Geographic Area: Butte County, the Oroville Quincy Highway from the Northeast corner of Lake Oroville along Canyon Creek to Bald Rock Road.

Length: 3.32 km (2.07 mi).

Target Species: Deer (*Odocoileus hemionus*).

Connectivity Concerns: This stretch of SR-162 is a noted spot for animal vehicle collision. Migratory deer from the Bucks Mountain/Mooretown deer herd winter here along with resident deer and make daily and seasonal movements across the highway. The riparian corridor along Canyon Creek is a draw for wildlife.

Remediation Goals: Expand and enhance existing infrastructure such as culverts and creek/river bridges, add new wildlife crossing structures and wildlife exclusion fencing.




Figure: SR-162 along Canyon Creek is a Region 2 wildlife connectivity barrier.