



Before Photo
Not Available

After Photo
Not Available

Site Name: SLANT PUMP

Stream Name: Sacramento River

Structure Owner: River Garden Farms Co.

Year Screened: 2011

Barrier Description Prior to Screening: Unscreened diversion

Site Description After Screening: Screened diversion

Site Status After Screening: Screened, fish response unconfirmed

Count of Total Barriers Downstream: 0

Count of Barriers with Unknown Passage Status Downstream: 11

Distance to Next Barrier Upstream with Barrier Status and PAD ID: 0.61 miles, Unscreened diversion, [700837](#)

Distance to Next Total Barrier Upstream with PAD ID: 120 miles, [718715](#)

PAD ID: [700831](#)

Tributary To: San Francisco Bay

Diversion Screened By: Not available

Barrier Status Prior to Screening: Unscreened diversion

Species Benefited After Screening: Not available

Count of Partial Barriers Downstream: 0

Count of Unscreened Diversions Downstream: 432

Distance to End of Natural Anadromy: Unknown

*Site statistics based on February 2013 version of the Passage Assessment Database