



After Photo
Not Available

Site Name: PORTUGUESE BEND PUMP PLANT SMWC

PAD ID: [700857](#)

Stream Name: Sacramento River

Tributary To: San Francisco Bay

Structure Owner: Sutter Mutual Water Co. / Frank Lamb Trust

Diversion Screened By: Not available

Year Screened: 2011

Barrier Status Prior to Screening: Unscreened diversion

Barrier Description Prior to Screening: Unscreened diversion

Species Benefited After Screening: Not available

Site Description After Screening: Screened diversion

Site Status After Screening: Screened, fish response unconfirmed

Count of Total Barriers Downstream: 0

Count of Partial Barriers Downstream: 0

Count of Barriers with Unknown Passage Status Downstream: 9

Count of Unscreened Diversions Downstream: 412

Distance to Next Barrier Upstream with Barrier Status and PAD ID: 0.04 miles, Unscreened diversion, [700855](#)

Distance to End of Natural Anadromy: Unknown

Distance to Next Total Barrier Upstream with PAD ID: 129 miles, [718715](#)

*Site statistics based on February 2013 version of the Passage Assessment Database