



- Barriers Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed

Before Photo  
Not Available



**Site Name:** Patterson Water District

**Stream Name:** San Joaquin River

**Structure Owner:** Private landowner(s) (non-corporate)

**Year Remediated:** 2011

**Site Type:** Diversion

**Site Status After Remediation:** Screened

**Species Benefited After Remediation:**

**Immediate Downstream barrier PAD ID:**

**PAD ID:** 700975

**Tributary To:** Sacramento River

**Barrier Remediation By:** Unknown

**Barrier Description Prior to Remediation:** Unscreened

**Count of Barriers Downstream:**

**Count of Barriers Upstream:**

**Distance Upstream to Next Barrier or Limit of Anadromy :** Miles

\*Site statistics based on June 2015 version of the Passage Assessment Database

**Notes:** Screening of this water diversion was funded by AFSP/ERP and implemented by FWA.