



- Barriers Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed



After Photo  
Not Available

**Site Name:** Davis Ranches #2 (Pump 4)

**Stream Name:** Sacramento River

**Structure Owner:** Private landowner(s) (non-corporate)

**Year Remediated:** 2010

**Site Type:** Diversion

**Site Status After Remediation:** Screened

**Species Benefited After Remediation:**

**Immediate Downstream barrier PAD ID:**

**Notes:** Screened to 65 cfs

**PAD ID:** 703609

**Tributary To:** San Francisco Bay

**Barrier Remediation By:** Unknown

**Barrier Description Prior to Remediation:** Unscreened

**Count of Barriers Downstream:**

**Count of Barriers Upstream:**

**Distance Upstream to Next Barrier or Limit of Anadromy :** Miles

\*Site statistics based on June 2015 version of the Passage Assessment Database