



- Barriers Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed



After Photo
Not Available

Site Name: Davis Ranches #2 (Pump 5)

Stream Name: Sacramento River

Structure Owner: Private landowner(s) (non-corporate)

Year Remediated: 2010

Site Type: Diversion

Site Status After Remediation: Screened

Species Benefited After Remediation:

Immediate Downstream barrier PAD ID:

Notes:

PAD ID: 703610

Tributary To: San Francisco Bay

Barrier Remediation By: Unknown

Barrier Description Prior to Remediation: Unscreened

Count of Barriers Downstream:

Count of Barriers Upstream:

Distance Upstream to Next Barrier or Limit of Anadromy : Miles

*Site statistics based on June 2015 version of the Passage Assessment Database