


- Barrier Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ☆ Unscreened Diversion
- Unknown Passage Status
- Unassessed



After Photo
Not Available

Site Name: Riverside Drive
Stream Name: Mill Creek (Watek Creek)
Structure Owner: Humboldt County
Year Remediated: 2011
Site Type: Road crossing
Site Status After Remediation: Remediated, fish response unconfirmed
Species Benefited After Remediation:
Immediate Downstream barrier PAD ID:

PAD ID: 705802
Tributary To: Mad River
Barrier Remediation By: Unknown
Barrier Description Prior to Remediation: Temporal
Count of Barriers Downstream:
Count of Barriers Upstream:
Distance Upstream to Next Barrier or Limit of Anadromy : Miles

*Site statistics based on June 2015 version of the Passage Assessment Database

Notes: Two culverts replaced with an embedded multiple box culvert to allow passage for salmonids. Before: Temporal barrier per professional judgement by Ross Taylor and Associates.