



Site Name: Culvert

Stream Name: Barker Creek

Structure Owner: U.S. Forest Service

Year Removed: 2011

Barrier Description Prior to Removal: Circular barrier

Site Description After Removal: Not available

Site Status After Removal: Remediated, fish response unconfirmed

Count of Total Barriers Downstream: 1 natural barrier

Count of Barriers with Unknown Passage Status Downstream: 23

Distance to Next Barrier Upstream with Barrier Status and PAD ID: 1.2 miles, Partial barrier, [713308](#)

Distance to Next Total Barrier Upstream with PAD ID: Not applicable

PAD ID: [707810](#)

Tributary To: Hayfork Creek

Barrier Removed By: Not available

Barrier Status Prior to Removal: Total barrier

Species Benefited After Removal: Not available

Count of Partial Barriers Downstream: 2

Count of Unscreened Diversions Downstream: 22

Distance to End of Natural Anadromy: Unknown

*Site statistics based on February 2013 version of the Passage Assessment Database