


- Barrier Remediated in 2011
- Section Opened to Fish Passage
- ⋯ Section Above Partial Barrier
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed

Before Photo
Not Available



After Photo
Not Available

Site Name: Soule Golf Course Crossing

Stream Name: San Antonio Creek

Structure Owner: Ventura County Parks

Year Removed: 2011

Barrier Description Prior to Removal: Dry weather crossing

Site Description After Removal: Bridge

Site Status After Removal: Remediated, fish response unconfirmed

Count of Total Barriers Downstream: 0

Count of Barriers with Unknown Passage Status Downstream: 6

Distance to Next Barrier Upstream with Barrier Status and PAD ID: 0.27 miles, Partial barrier, [713873](#)

Distance to Next Total Barrier Upstream with PAD ID: 0.60 miles, [705670](#)

PAD ID: [713872](#)

Tributary To: Ventura River

Barrier Removed By: Not available

Barrier Status Prior to Removal: Total barrier

Species Benefited After Removal: Not available

Count of Partial Barriers Downstream: 5

Count of Unscreened Diversions Downstream: 0

Distance to End of Natural Anadromy: Unknown

*Site statistics based on February 2013 version of the Passage Assessment Database