



Before Photo
Not Available

After Photo
Not Available

Site Name: Robles Diversion Dam & Downstream Weir

Stream Name: Ventura River

Structure Owner: U.S. Bureau of Reclamation

Year Removed: 2011

Barrier Description Prior to Removal: Barrier to fish passage under most flow conditions

Site Description After Removal: Variety of structures added to ensure safe passage of fish

Site Status After Removal: Remediated, fish response unconfirmed

Count of Total Barriers Downstream: 0

Count of Barriers with Unknown Passage Status Downstream: 5

Distance to Next Barrier Upstream with Barrier Status and PAD ID: 1.87 miles, Partial barrier, [713885](#)

Distance to Next Total Barrier Upstream with PAD ID: 2.12 miles, [719058](#)

PAD ID: [713886](#)

Tributary To: Pacific

Barrier Removed By: Not available

Barrier Status Prior to Removal: Partial barrier

Species Benefited After Removal: Not available

Count of Partial Barriers Downstream: 1

Count of Unscreened Diversions Downstream: 0

Distance to End of Natural Anadromy: Unknown

*Site statistics based on February 2013 version of the Passage Assessment Database