



Before Photo
Not Available

After Photo
Not Available

Site Name: Road 81-M Culvert

Stream Name: Neefus Gulch

Structure Owner: Mendocino Redwood Company

Year Removed: 2011

Barrier Description Prior to Removal: Not available

Site Description After Removal: Not available

Site Status After Removal: Remediated, fish response unconfirmed

Count of Total Barriers Downstream: 0

Count of Barriers with Unknown Passage Status Downstream: 1

Distance to Next Barrier Upstream with Barrier Status and PAD ID: 0.37 miles, Total barrier, [758252](#)

Distance to Next Total Barrier Upstream with PAD ID: 0.37 miles, [758252](#)

PAD ID: [723503](#)

Tributary To: North Fork Navarro River

Barrier Removed By: Not available

Barrier Status Prior to Removal: Unknown

Species Benefited After Removal: Not available

Count of Partial Barriers Downstream: 0

Count of Unscreened Diversions Downstream: 0

Distance to End of Natural Anadromy: Unknown

*Site statistics based on February 2013 version of the Passage Assessment Database