



- Barrier Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed

Before Photo  
Not Available



After Photo  
Not Available

**Site Name:** Janes Creek Culvert 1 Fish Passage Improvement Project

**Stream Name:** Janes Creek

**Structure Owner:**

**Year Remediated:** 2011

**Site Type:** Road crossing

**Site Status After Remediation:** Remediated, fish response unconfirmed

**Species Benefited After Remediation:**

**Immediate Downstream barrier PAD ID:**

**Notes:** South Fork Janes Creek Instream Barrier Removal Phase II. Before: Temporal barrier.

**PAD ID:** [723657](#)

**Tributary To:** McDaniel Slough

**Barrier Remediation By:** Unknown

**Barrier Description Prior to Remediation:** Temporal

**Count of Barriers Downstream:**

**Count of Barriers Upstream:**

**Distance Upstream to Next Barrier or Limit of Anadromy :** Miles

\*Site statistics based on June 2015 version of the Passage Assessment Database