



- Barrier Remediated in 2011
- Section Opened to Fish Passage
- ⋯ Section Above Partial Barrier
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed



After Photo
Not Available

Site Name: Refugio Road Low-flow Xing-2

Stream Name: Quiota Creek

Structure Owner: Santa Barbara County Public Works-Roads Division

Year Removed: 2011

Barrier Description Prior to Removal: Low flow road crossing

Site Description After Removal: Not available

Site Status After Removal: Remediated, fish response unconfirmed

Count of Total Barriers Downstream: 0

Count of Barriers with Unknown Passage Status Downstream: 2

Distance to Next Barrier Upstream with Barrier Status and PAD ID: 0.6 miles, Partial barrier, [723689](#)

Distance to Next Total Barrier Upstream with PAD ID: 0.17 miles, [723690](#)

PAD ID: [723688](#)

Tributary To: Santa Ynez River

Barrier Removed By: Not available

Barrier Status Prior to Removal: Total barrier

Species Benefited After Removal: Not available

Count of Partial Barriers Downstream: 3

Count of Unscreened Diversions Downstream: 0

Distance to End of Natural Anadromy: Unknown

*Site statistics based on February 2013 version of the Passage Assessment Database