



After Photo
Not Available

Site Name: Road #550

Stream Name: North Fork Berry Gulch

Structure Owner: Jackson State Forest

Year Removed:

Barrier Description Prior to Removal: Excessive velocity due to slope

Site Description After Removal: Culvert removed

Site Status After Removal: Remediated, fish response unconfirmed

Count of Total Barriers Downstream: 0

Count of Barriers with Unknown Passage Status Downstream: 0

Distance to Next Barrier Upstream with Barrier Status and PAD ID: No known barriers remaining upstream

Distance to Next Total Barrier Upstream with PAD ID: Not applicable

PAD ID: [736911](#)

Tributary To: Little North Fork Big River

Barrier Removed By: Not available

Barrier Status Prior to Removal: Temporal & Partial

Species Benefited After Removal: Not available

Count of Partial Barriers Downstream: 2

Count of Unscreened Diversions Downstream: 0

Distance to End of Natural Anadromy: Unknown

*Site statistics based on February 2013 version of the Passage Assessment Database