


- Barrier Remediated in 2011
- Section Opened to Fish Passage
- ⋯ Section Above Partial Barrier
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed



After Photo
Not Available

Site Name: Nevada Irrigation District Gaging Station

Stream Name: Auburn Ravine

Structure Owner: Nevada Irrigation District

Year Removed: 2011

Barrier Description Prior to Removal: Significant impediment to upstream migration at all but extremely high flows.

Site Description After Removal: Fish ladder

Site Status After Removal: Remediated, fish response unconfirmed

Count of Total Barriers Downstream: 0

Count of Barriers with Unknown Passage Status Downstream: 4

Distance to Next Barrier Upstream with Barrier Status and PAD ID: 3.28 miles, Partial barrier, [737315](#)

Distance to Next Total Barrier Upstream with PAD ID: Not applicable

PAD ID: [737308](#)

Tributary To: Coon Creek

Barrier Removed By: Not available

Barrier Status Prior to Removal: Total barrier

Species Benefited After Removal: Not available

Count of Partial Barriers Downstream: 2

Count of Unscreened Diversions Downstream: 405

Distance to End of Natural Anadromy: Unknown

*Site statistics based on February 2013 version of the Passage Assessment Database