



Before Photo
Not Available



After Photo
Not Available

Site Name: Lompico Creek Log Jam

Stream Name: Lompico Creek

Structure Owner: Not available

Year Removed: 2011

Barrier Description Prior to Removal: Log jam

Site Description After Removal: Log jam removed

Site Status After Removal: Remediated, fish response unconfirmed

Count of Total Barriers Downstream: 0

Count of Barriers with Unknown Passage Status Downstream: 1

Distance to Next Barrier Upstream with Barrier Status and PAD ID: 0.4 miles, Partial barrier, [706768](#)

Distance to Next Total Barrier Upstream with PAD ID: Not applicable

PAD ID: [758250](#)

Tributary To: Zayante Creek

Barrier Removed By: Not available

Barrier Status Prior to Removal: Not available

Species Benefited After Removal: Not available

Count of Partial Barriers Downstream: 6

Count of Unscreened Diversions Downstream: 0

Distance to End of Natural Anadromy: Unknown

*Site statistics based on February 2013 version of the Passage Assessment Database