



After Photo
Not Available

Site Name: FISH LADDER ACROSS ZINFANDEL BRIDGE

Stream Name: Napa River

Structure Owner: County of Napa

Year Removed: 2011

Barrier Description Prior to Removal: Concrete apron blocked Chinook and steelhead from swimming upstream and interfered with juveniles swimming downstream

Site Description After Removal: Concrete apron has been removed

Site Status After Removal: Remediated, fish response unconfirmed

Count of Total Barriers Downstream: 0

Count of Barriers with Unknown Passage Status Downstream: 2

Distance to Next Barrier Upstream with Barrier Status and PAD ID: 0.11 miles, Unscreened diversion, [704258](#)

Distance to Next Total Barrier Upstream with PAD ID: 5.17 miles, [735062](#)

PAD ID: [704250](#)

Tributary To: San Pablo Bay

Barrier Removed By: Not available

Barrier Status Prior to Removal: Partial barrier

Species Benefited After Removal: Not available

Count of Partial Barriers Downstream: 3

Count of Unscreened Diversions Downstream: 44

Distance to End of Natural Anadromy: Unknown

*Site statistics based on February 2013 version of the Passage Assessment Database