


- Barrier Remediated in 2011
- Section Opened to Fish Passage
- - - Section Above Partial Barrier
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ★ Unscreened Diversion
- Unknown Passage Status
- Unassessed



Site Name: Conner Creek Rd. box culvert

Stream Name: Conner Creek

Structure Owner: Trinity County

Year Removed: 2011

Barrier Description Prior to Removal: 10 foot box culvert that failed to meet passage criteria for all species of adult salmonids and all age classes of juveniles.

Site Description After Removal: Not available

Site Status After Removal: Remediated, fish response unconfirmed

Count of Total Barriers Downstream: 0

Count of Barriers with Unknown Passage Status Downstream: 26

Distance to Next Barrier Upstream with Barrier Status and PAD ID: No known barriers remaining upstream

Distance to Next Total Barrier Upstream with PAD ID: Not applicable

PAD ID: [705962](#)

Tributary To: Trinity River

Barrier Removed By: Not available

Barrier Status Prior to Removal: Total barrier

Species Benefited After Removal: Not available

Count of Partial Barriers Downstream: 0

Count of Unscreened Diversions Downstream: 41

Distance to End of Natural Anadromy: Unknown

*Site statistics based on February 2013 version of the Passage Assessment Database