


Before Photo
Not Available



After Photo
Not Available

Site Name: Freshwater Creek Barrier Modification

Stream Name: Freshwater Creek

Structure Owner: Not available

Year Removed: 2011

Barrier Description Prior to Removal: Log jam with jump height greater than three feet

Site Description After Removal: Reduced jump height to less than three feet

Site Status After Removal: Remediated, fish response unconfirmed

Count of Total Barriers Downstream: 1

Count of Barriers with Unknown Passage Status Downstream: 0

Distance to Next Barrier Upstream with Barrier Status and PAD ID: 1.37 miles, Unknown barrier, [717148](#)

Distance to Next Total Barrier Upstream with PAD ID: Not applicable

PAD ID: [736877](#)

Tributary To: Eureka Slough

Barrier Removed By: Not available

Barrier Status Prior to Removal: Unknown barrier

Species Benefited After Removal: Not available

Count of Partial Barriers Downstream: 3

Count of Unscreened Diversions Downstream: 0

Distance to End of Natural Anadromy: 0.5 miles

*Site statistics based on February 2013 version of the Passage Assessment Database