



Site Name: Low flow Arizona Crossing (ford, T5) on Tajiguas Creek

Stream Name: Tajiguas Creek

Structure Owner: Not available

Year Removed: 2011

Barrier Description Prior to Removal: Low flow Arizona crossing

Site Description After Removal: Natural streambed crossing

Site Status After Removal: Remediated, fish response unconfirmed

Count of Total Barriers Downstream: 1

Count of Barriers with Unknown Passage Status Downstream: 2

Distance to Next Barrier Upstream with Barrier Status and PAD ID: 0.99 miles, Unknown barrier, [706360](#)

Distance to Next Total Barrier Upstream with PAD ID: 1.14 miles, [706363](#)

PAD ID: [758546](#)

Tributary To: Pacific

Barrier Removed By: Not available

Barrier Status Prior to Removal: Not available

Species Benefited After Removal: Not available

Count of Partial Barriers Downstream: 0

Count of Unscreened Diversions Downstream: 0

Distance to End of Natural Anadromy: Unknown

*Site statistics based on February 2013 version of the Passage Assessment Database