

STREAM INVENTORY REPORT

Bean Creek

INTRODUCTION

A stream inventory was conducted during the summer of 1997 on Bean Creek. The inventory was conducted in two parts: habitat inventory and biological inventory. The objective of the habitat inventory was to document the habitat available to anadromous salmonids in Bean Creek. The objective of the biological inventory was to document the presence and distribution of juvenile salmonid species.

The objective of this report is to document the current habitat conditions, and recommend options for the potential enhancement of habitat for coho salmon and steelhead trout. Recommendations for habitat improvement activities are based upon target habitat values suitable for salmonids in California's north coast streams.

WATERSHED OVERVIEW

Bean Creek is a tributary to Tomki Creek, a tributary to the Eel River, which drains to the Pacific Ocean. It is located in Mendocino County, California. Bean Creek's legal description at the confluence with Tomki Creek is T19N R13W S05. Its location is 39.5281 degrees north latitude and 123.3222 degrees west longitude. Bean Creek is a first order stream and has approximately 3.8 miles of blue line stream according to the USGS Willis Ridge 7.5 minute quadrangle. Bean Creek drains a watershed of approximately 1.3 square miles. Elevations range from about 1,960 feet at the mouth of the creek to 2,680 feet in the headwater areas. Douglas fir forest and mixed hardwood forest dominate the watershed. The watershed is entirely privately owned. Vehicle access exists via Highway 101 to Willits. Take first left after Reeves Canyon Road. Stay on the main road to the creek.

METHODS

The habitat inventory conducted in Bean Creek follows the methodology presented in the *California Salmonid Stream Habitat Restoration Manual* (Flosi et al, 1998). The California Conservation Corps (CCC) Technical Advisors and Watershed Stewards Project/AmeriCorps (WSP/AmeriCorps) Members that conducted the inventory were trained in standardized habitat inventory methods by the California Department of Fish and Game (DFG). This inventory was conducted by a two-person team.

SAMPLING STRATEGY

The inventory uses a method that samples approximately 10% of the habitat units within the survey reach. All habitat units included in the survey are classified according to habitat type and their lengths are measured. All pool units are measured for maximum depth, depth of pool tail

Bean Creek

crest (measured in the thalweg), dominant substrate composing the pool tail crest, and embeddedness. Habitat unit types encountered for the first time are measured for all the parameters and characteristics on the field form. Additionally, from the ten habitat units on each field form page, one is randomly selected for complete measurement.

HABITAT INVENTORY COMPONENTS

A standardized habitat inventory form has been developed for use in California stream surveys and can be found in the *California Salmonid Stream Habitat Restoration Manual*. This form was used in Bean Creek to record measurements and observations. There are nine components to the inventory form.

1. Flow:

Flow is measured in cubic feet per second (cfs) at the bottom of the stream survey reach using a Marsh-McBirney Model 2000 flow meter.

2. Channel Type:

Channel typing is conducted according to the classification system developed and revised by David Rosgen (1985 rev. 1994). This methodology is described in the *California Salmonid Stream Habitat Restoration Manual*. Channel typing is conducted simultaneously with habitat typing and follows a standard form to record measurements and observations. There are five measured parameters used to determine channel type: 1) water slope gradient, 2) entrenchment, 3) width/depth ratio, 4) substrate composition, and 5) sinuosity. Channel characteristics are measured using a clinometer, hand level, hip chain, tape measure, and a stadia rod.

3. Temperatures:

Both water and air temperatures are measured and recorded at every tenth habitat unit. The time of the measurement is also recorded. Both temperatures are taken in degrees Fahrenheit at the middle of the habitat unit and within one foot of the water surface.

4. Habitat Type:

Habitat typing uses the 24 habitat classification types defined by McCain and others (1988). Habitat units are numbered sequentially and assigned a type identification number selected from a standard list of 24 habitat types. Dewatered units are labeled "dry". Bean Creek habitat typing used standard basin level measurement criteria. These parameters require that the minimum length of a described habitat unit must be equal to or greater than the stream's mean wetted width. All measurements are in feet to the nearest tenth. Habitat characteristics are measured using a clinometer, hip chain, and stadia rod.

Bean Creek

5. Embeddedness:

The depth of embeddedness of the cobbles in pool tail-out areas is measured by the percent of the cobble that is surrounded or buried by fine sediment. In Bean Creek, embeddedness was ocularly estimated. The values were recorded using the following ranges: 0 - 25% (value 1), 26 - 50% (value 2), 51 - 75% (value 3) and 76 - 100% (value 4). Additionally, a value of 5 was assigned to tail-outs deemed not suitable for spawning due to inappropriate substrate particle size, bedrock, or other considerations.

6. Shelter Rating:

Instream shelter is composed of those elements within a stream channel that provide salmonids protection from predation, reduce water velocities so fish can rest and conserve energy, and allow separation of territorial units to reduce density related competition. The shelter rating is calculated for each fully-described habitat unit by multiplying shelter value and percent cover. Using an overhead view, a quantitative estimate of the percentage of the habitat unit covered is made. All cover is then classified according to a list of nine cover types. In Bean Creek, a standard qualitative shelter value of 0 (none), 1 (low), 2 (medium), or 3 (high) was assigned according to the complexity of the cover. Thus, shelter ratings can range from 0-300 and are expressed as mean values by habitat types within a stream.

7. Substrate Composition:

Substrate composition ranges from silt/clay sized particles to boulders and bedrock elements. In all fully-described habitat units, dominant and sub-dominant substrate elements were ocularly estimated using a list of seven size classes and recorded as a one and two, respectively. In addition, the dominant substrate composing the pool tail-outs is recorded for each pool.

8. Canopy:

Stream canopy density was estimated using modified handheld spherical densimeters as described in the *California Salmonid Stream Habitat Restoration Manual*. Canopy density relates to the amount of stream shaded from the sun. In Bean Creek, an estimate of the percentage of the habitat unit covered by canopy was made from the center of approximately every third unit in addition to every fully-described unit, giving an approximate 30% sub-sample. In addition, the area of canopy was estimated ocularly into percentages of coniferous or deciduous trees.

9. Bank Composition and Vegetation:

Bank composition elements range from bedrock to bare soil. However, the stream banks are usually covered with grass, brush, or trees. These factors influence the ability of stream banks to withstand winter flows. In Bean Creek, the dominant composition type and the dominant vegetation type of both the right and left banks for each fully-described unit were selected from the habitat inventory form. Additionally, the percent of each bank covered by vegetation (including downed trees, logs, and rootwads) was estimated and recorded.

Bean Creek

BIOLOGICAL INVENTORY

Biological sampling during the stream inventory is used to determine fish species and their distribution in the stream. Fish presence was observed from the stream banks in Bean Creek, and one site was electrofished using a Smith-Root Model 12 electrofisher. These sampling techniques are discussed in the *California Salmonid Stream Habitat Restoration Manual*.

DATA ANALYSIS

Data from the habitat inventory form are entered into Habitat, a dBASE 4.2 data entry program developed by Tim Curtis, Inland Fisheries Division, California Department of Fish and Game. This program processes and summarizes the data, and produces the following six tables:

- Riffle, flatwater, and pool habitat types
- Habitat types and measured parameters
- Pool types
- Maximum pool depths by habitat types
- Dominant substrates by habitat types
- Mean percent shelter by habitat types

Graphics are produced from the tables using Quattro Pro. Graphics developed for Bean Creek include:

- Riffle, flatwater, pool habitats by percent occurrence
- Riffle, flatwater, pool habitats by total length
- Total habitat types by percent occurrence
- Pool types by percent occurrence
- Total pools by maximum depths
- Embeddedness
- Pool cover by cover type
- Dominant substrate in low gradient riffles
- Mean percent canopy
- Bank composition by composition type
- Bank vegetation by vegetation type

HABITAT INVENTORY RESULTS

The habitat inventory of July 16, 1997 was conducted by Allan Renger (CCC) and Jessie Robertson (WSP).

Flow was measured during the survey period with a Marsh-McBirney Model 2000 flowmeter at 0.09 cfs on July 17, 1997.

Bean Creek

Bean Creek is a B4 channel type for the entire 1,715 feet of stream reach surveyed. B4 channels are: moderately entrenched, moderate gradient, riffle dominated gravel channels with infrequently spaced pools, very stable plan and profile, and stable banks.

Water temperatures taken during the survey period ranged from 63 to 69 degrees Fahrenheit. Air temperatures ranged from 73 to 84 degrees Fahrenheit.

Table 1 summarizes the Level II riffle, flatwater, and pool habitat types. Based on frequency of occurrence there were 46% riffle units, 24% flatwater units, 24% pool units, and 5% dry units (Graph 1). Based on total length of Level II habitat types there were 57% riffle units, 26% flatwater units, 13% pool units, and 5% dry units (Graph 2).

Four Level IV habitat types were identified (Table 2). The most frequent habitat types by percent occurrence were low gradient riffles, 46%; main channel pools, 24%; and runs, 16% (Graph 3). Based on percent total length, low gradient riffles made up 57%, step runs 15%, and main channel pools 13%.

A total of nine pools were identified (Table 3). Main channel pools comprised 100% of the pools encountered and 100% of the total length of all pools (Graph 4).

Table 4 is a summary of maximum pool depths by pool habitat types. Pool quality for salmonids increases with depth. Three of the nine pools (33%) had a depth of two feet or greater (Graph 5).

The depth of cobble embeddedness was estimated at pool tail-outs. Of the nine pool tail-outs measured, three had a value of 1 (33%); four had a value of 2 (45%); and two had a value of 3 (22%); (Graph 6). On this scale, a value of 1 indicates the highest quality of spawning substrate. In Bean Creek, none of the pool tail-outs contained substrate unsuitable for spawning.

A shelter rating was calculated for each habitat unit and expressed as a mean value for each habitat type within the survey using a scale of 0-300. Riffle habitat types had a mean shelter rating of 20, flatwater habitat types had a mean shelter rating of 15, and pool habitats had a mean shelter rating of 5 (Table 1). Main channel pools had a mean shelter rating of 5 (Table 3).

Table 5 summarizes mean percent cover by habitat type. Boulders are the dominant cover type in Bean Creek. Small and large woody debris are lacking in nearly all habitat types. Graph 7 describes the pool cover in Bean Creek.

Table 6 summarizes the dominant substrate by habitat type. Gravel was the dominant substrate observed in seven of the nine pool tail outs measured (78%). Small cobble was the next most frequently observed dominant substrate type and occurred in the remaining two pool tail outs (Graph 8).

The mean percent canopy density for the stream reach surveyed was 37%. The mean percentages of deciduous and coniferous trees were 94% and 6%, respectively. Graph 9 describes the canopy composition in Bean Creek.

Bean Creek

For the stream reach surveyed, the mean percent right bank vegetated was 67%. The mean percent left bank vegetated was 59%. The dominant elements composing the structure of the stream banks consisted of 79% cobble/gravel, 14% bedrock, and 7% boulders (Graph 10). Brush and deciduous trees were the dominant vegetation type observed in the units surveyed. No other vegetation types were observed (Graph 11).

BIOLOGICAL INVENTORY RESULTS

One Bean Creek site was electrofished on July 17, 1997. The site was sampled by Allan Renger (CCC) and Jessie Robertson (WSP).

The sample site included Habitat Units #020 and #021, located approximately 834 feet from the confluence with Tomki Creek. This site had an area of 392 square feet and a volume of 235 cubic feet. The site yielded one young-of-the-year steelhead/rainbow trout, one age 1+ steelhead/rainbow trout, and two rough skinned newts.

DISCUSSION

Bean Creek is a B4 channel type for the entire 1,715 feet of stream surveyed. The suitability of B4 channel types for fish habitat improvement structures is as follows: excellent for low-stage plunge weirs; boulder clusters and bank placed boulders; single and opposing wing-deflectors; and log cover.

The water temperatures recorded on the survey day July 17, 1997 ranged from 63 to 69 degrees Fahrenheit. Air temperatures ranged from 73 to 84 degrees Fahrenheit. This water temperature range is near the threshold stress level for salmonids. To make any further conclusions, temperatures need to be monitored throughout the warm summer months, and more extensive biological sampling needs to be conducted.

Flatwater habitat types comprised 26% of the total length of this survey, riffles 57%, pools 13%, and dry 5%. The pools are relatively shallow, with only three of the nine (33%) pools having a maximum depth greater than two feet. In general, pool enhancement projects are considered when primary pools comprise less than 40% of the length of total stream habitat. In first and second order streams, a primary pool is defined to have a maximum depth of at least two feet, occupy at least half the width of the low flow channel, and be as long as the low flow channel width. Installing structures that will increase or deepen pool habitat is recommended.

Three of the nine pool tail-outs measured had an embeddedness rating of 1. Four of the pool tail-outs had an embeddedness rating of 2. Two of the pool tail-outs had embeddedness ratings of 3 or 4. None of the pool tail-outs had a rating of 5, which is considered not suitable for spawning. Cobble embeddedness measured to be 25% or less, a rating of 1, is considered to indicate good quality spawning substrate for salmon and steelhead.

Bean Creek

The mean shelter rating for pools was 5. The shelter rating in the flatwater habitats was 15. A pool shelter rating of approximately 100 is desirable. The relatively small amount of cover that now exists is being provided primarily by boulders in all habitat types. Additionally, root mass contributes a small amount. Log and root wad cover structures in the pool and flatwater habitats are needed to improve both summer and winter salmonid habitat. Log cover structures provide rearing fry with protection from predation, rest from water velocity, and also divide territorial units to reduce density related competition.

One hundred percent of the pool tail outs measured had gravel or small cobble as the dominant substrate. This is generally considered good for spawning salmonids.

The mean percent canopy density for the stream was 37%. In general, revegetation projects are considered when canopy density is less than 80%.

The percentage of right and left bank covered with vegetation was moderate at 67% and 59%, respectively. In areas of stream bank erosion or where bank vegetation is at unacceptable levels, planting endemic species of coniferous and deciduous trees, in conjunction with bank stabilization, is recommended.

RECOMMENDATIONS

- 1) Bean Creek should be managed as an anadromous, natural production stream.
- 2) Increase the canopy on Bean Creek by planting willow, alder, redwood, and Douglas fir along the stream where shade canopy is not at acceptable levels. The reaches above this survey section should be inventoried and treated as well, since the water flowing here is effected from upstream. In many cases, planting will need to be coordinated to follow bank stabilization or upslope erosion control projects.
- 3) Increase woody cover in the pools and flatwater habitat units. Most of the existing cover is from boulders. Adding high quality complexity with woody cover is desirable.
- 4) Where feasible, design and engineer pool enhancement structures to increase the number of pools. This must be done where the banks are stable or in conjunction with stream bank armor to prevent erosion.
- 5) The limited water temperature data available suggest that maximum temperatures are near the threshold stress level for juvenile salmonids. To establish more complete and meaningful temperature regime information, 24-hour monitoring during the July and August temperature extreme period should be performed for 3 to 5 years.

Bean Creek

COMMENTS AND LANDMARKS

The following landmarks and possible problem sites were noted. All distances are approximate and taken from the beginning of the survey reach.

Position Comments:
(ft):

0'	Start of survey at confluence with Tomki Creek. Channel type is B4.
834'	Electrofishing site.
1,715'	End of survey due to slides on both banks clogging the channel and creating a fish barrier.

REFERENCES

Flosi, G., Downie, S., Hopelain, J., Bird, M., Coey, R., and Collins, B. 1998. *California Salmonid Stream Habitat Restoration Manual*, 3rd edition. California Department of Fish and Game, Sacramento, California.

Bean Creek

LEVEL III and LEVEL IV HABITAT TYPE KEY

HABITAT TYPE	LETTER	NUMBER
RIFFLE		
Low Gradient Riffle	[LGR]	1.1
High Gradient Riffle	[HGR]	1.2
CASCADE		
Cascade	[CAS]	2.1
Bedrock Sheet	[BRS]	2.2
FLATWATER		
Pocket Water	[POW]	3.1
Glide	[GLD]	3.2
Run	[RUN]	3.3
Step Run	[SRN]	3.4
Edgewater	[EDW]	3.5
MAIN CHANNEL POOLS		
Trench Pool	[TRP]	4.1
Mid-Channel Pool	[MCP]	4.2
Channel Confluence Pool	[CCP]	4.3
Step Pool	[STP]	4.4
SCOUR POOLS		
Corner Pool	[CRP]	5.1
Lateral Scour Pool - Log Enhanced	[LSL]	5.2
Lateral Scour Pool - Root Wad Enhanced	[LSR]	5.3
Lateral Scour Pool - Bedrock Formed	[LSBk]	5.4
Lateral Scour Pool - Boulder Formed	[LSBo]	5.5
Plunge Pool	[PLP]	5.6
BACKWATER POOLS		
Secondary Channel Pool	[SCP]	6.1
Backwater Pool - Boulder Formed	[BPB]	6.2
Backwater Pool - Root Wad Formed	[BPR]	6.3
Backwater Pool - Log Formed	[BPL]	6.4
Dammed Pool	[DPL]	6.5