STREAM INVENTORY REPORT

Unnamed Tributary to Redwood Creek

INTRODUCTION

A stream inventory was conducted from June 11 to June 13, 2012 on an unnamed tributary to Redwood Creek. The survey began at the confluence with Redwood Creek and extended upstream 0.8 miles. A stream inventory and report was also completed for one tributary to the unnamed tributary.

The unnamed tributary inventory was conducted in two parts: habitat inventory and biological inventory. The objective of the habitat inventory was to document the habitat available to anadromous salmonids in the unnamed tributary. The objective of the biological inventory was to document the presence and distribution of juvenile salmonid species.

The objective of this report is to document the current habitat conditions and recommend options for the potential enhancement of habitat for coho salmon and steelhead trout. Recommendations for habitat improvement activities are based upon target habitat values suitable for salmonids in California's north coast streams.

WATERSHED OVERVIEW

The unnamed tributary is a tributary to Redwood Creek, tributary to South Fork Ten Mile River, tributary to Ten Mile River, which drains to the Pacific Ocean. It is located in Mendocino County, California (Map 1). The unnamed tributary's legal description at the confluence with Redwood Creek is T19N R16W S12. Its location is 39.5110 degrees north latitude and 123.5933 degrees west longitude, LLID number 1235921395111. The unnamed tributary is a first order stream and has approximately 0.3 miles of blue line stream according to the USGS Sherwood Peak 7.5 minute quadrangle. The unnamed tributary drains a watershed of approximately 1.7 square miles. Elevations range from about 500 feet at the mouth of the creek to 1,000 feet in the headwater areas. Mixed conifer forest dominates the watershed. The watershed is entirely privately owned and is managed for timber production. Vehicle access exists via Camp One Ten Mile Road north of Fort Bragg.

METHODS

The habitat inventory conducted in the unnamed tributary follows the methodology presented in the *California Salmonid Stream Habitat Restoration Manual* (Flosi et al, 1998). The Watershed Stewards Project/AmeriCorps (WSP) members that conducted the inventory were trained in standardized habitat inventory methods by the California Department of Fish and Wildlife (CDFW). This inventory was conducted by a two-person team.

SAMPLING STRATEGY

The inventory uses a method that samples approximately 10% of the habitat units within the survey reach. All habitat units included in the survey are classified according to habitat type and their lengths are measured. All pool units are measured for maximum depth, depth of pool tail crest (measured in the thalweg), dominant substrate composing the pool tail crest, and embeddedness. Habitat unit types encountered for the first time are measured for all the parameters and characteristics on the field form. Additionally, from the ten habitat units on each field form page, one is randomly selected for complete measurement.

HABITAT INVENTORY COMPONENTS

A standardized habitat inventory form has been developed for use in California stream surveys and can be found in the *California Salmonid Stream Habitat Restoration Manual*. This form was used in the unnamed tributary to record measurements and observations. There are eleven components to the inventory form.

1. Flow:

Flow is measured in cubic feet per second (cfs) near the bottom of the stream survey reach using a Marsh-McBirney Model 2000 flow meter.

2. Channel Type:

Channel typing is conducted according to the classification system developed and revised by David Rosgen (1994). This methodology is described in the *California Salmonid Stream Habitat Restoration Manual*. Channel typing is conducted simultaneously with habitat typing and follows a standard form to record measurements and observations. There are five measured parameters used to determine channel type: 1) water slope gradient, 2) entrenchment, 3) width/depth ratio, 4) substrate composition, and 5) sinuosity. Channel characteristics are measured using a clinometer, hand level, hip chain, tape measure, and a stadia rod.

3. Temperatures:

Both water and air temperatures are measured and recorded at every tenth habitat unit. The time of the measurement is also recorded. Both temperatures are taken in degrees Fahrenheit at the middle of the habitat unit and within one foot of the water surface.

4. Habitat Type:

Habitat typing uses the 24 habitat classification types defined by McCain and others (1990). Habitat units are numbered sequentially and assigned a type identification number selected from a standard list of 24 habitat types. Dewatered units are labeled "dry". The unnamed tributary habitat typing used standard basin level measurement criteria. These parameters require that the minimum length of a described habitat unit must be equal to or greater than the stream's mean

wetted width. All measurements are in feet to the nearest tenth. Habitat characteristics are measured using a clinometer, hip chain, and stadia rod.

5. Embeddedness:

The depth of embeddedness of the cobbles in pool tail-out areas is measured by the percent of the cobble that is surrounded or buried by fine sediment. In the unnamed tributary, embeddedness was ocularly estimated. The values were recorded using the following ranges: 0 - 25% (value 1), 26 - 50% (value 2), 51 - 75% (value 3) and 76 - 100% (value 4). Additionally, a value of 5 was assigned to tail-outs deemed not suitable for spawning due to inappropriate substrate like bedrock, log sills, boulders or other considerations.

6. Shelter Rating:

Instream shelter is composed of those elements within a stream channel that provide juvenile salmonids protection from predation, reduce water velocities so fish can rest and conserve energy, and allow separation of territorial units to reduce density related competition for prey. Using an overhead view, a quantitative estimate of the percentage of the habitat unit covered is made. All cover is classified according to a list of nine cover types. In the unnamed tributary, a standard qualitative shelter value of 0 (none), 1 (low), 2 (medium), or 3 (high) was assigned according to the complexity of the cover. The shelter rating is then calculated for each fully-described habitat unit by multiplying shelter value and percent cover. Thus, shelter ratings can range from 0-300 and are expressed as mean values by habitat types within a stream.

7. Substrate Composition:

Substrate composition ranges from silt/clay sized particles to boulders and bedrock elements. In all fully-described habitat units, dominant and sub-dominant substrate elements were ocularly estimated using a list of seven size classes and recorded as a one and two, respectively. In addition, the dominant substrate composing the pool tail-outs is recorded for each pool.

8. Canopy:

Stream canopy density was estimated using modified handheld spherical densiometers as described in the *California Salmonid Stream Habitat Restoration Manual*. Canopy density relates to the amount of stream shaded from the sun. In the unnamed tributary, an estimate of the percentage of the habitat unit covered by canopy was made from the center of approximately every third unit in addition to every fully-described unit, giving an approximate 30% sub-sample. In addition, the area of canopy was estimated ocularly into percentages of coniferous or hardwood trees.

9. Bank Composition and Vegetation:

Bank composition elements range from bedrock to bare soil. However, the stream banks are usually covered with grass, brush, or trees. These factors influence the ability of stream banks to withstand winter flows. In the unnamed tributary, the dominant composition type and the

dominant vegetation type of both the right and left banks for each fully-described unit were selected from the habitat inventory form. Additionally, the percent of each bank covered by vegetation (including downed trees, logs, and rootwads) was estimated and recorded.

10. Large Woody Debris Count:

Large woody debris (LWD) is an important component of fish habitat and an element in channel forming processes. In each habitat unit all pieces of LWD partially or entirely below the elevation of bankfull discharge are counted and recorded. The minimum size to be considered is twelve inches in diameter and six feet in length. The LWD count is presented by reach and is expressed as an average per 100 feet.

11. Average Bankfull Width:

Bankfull width can vary greatly in the course of a channel type stream reach. This is especially true in very long reaches. Bankfull width can be a factor in habitat components like canopy density, water temperature, and pool depths. Frequent measurements taken at riffle crests (velocity crossovers) are needed to accurately describe reach widths. At the first appropriate velocity crossover that occurs after the beginning of a new stream survey page (ten habitat units), bankfull width is measured and recorded in the appropriate header block of the page. These widths are presented as an average for the channel type reach.

BIOLOGICAL INVENTORY

Biological sampling during the stream inventory is used to determine fish species and their distribution in the stream. Fish presence was observed from the stream banks in the unnamed tributary. In addition, underwater observations were made at nine sites using techniques discussed in the *California Salmonid Stream Habitat Restoration Manual*.

DATA ANALYSIS

Data from the habitat inventory form are entered into Stream Habitat 2.0.19, a Visual Basic data entry program developed by Karen Wilson, Pacific States Marine Fisheries Commission in conjunction with the California Department of Fish and Wildlife. This program processes and summarizes the data, and produces the following ten tables:

- Riffle, Flatwater, and Pool Habitat Types
- Habitat Types and Measured Parameters
- Pool Types
- Maximum Residual Pool Depths by Habitat Types
- Mean Percent Cover by Habitat Type
- Dominant Substrates by Habitat Type
- Mean Percent Vegetative Cover for Entire Stream
- Fish Habitat Inventory Data Summary by Stream Reach (Table 8)

- Mean Percent Dominant Substrate / Dominant Vegetation Type for Entire Stream
- Mean Percent Shelter Cover Types for Entire Stream

Graphics are produced from the tables using Microsoft Excel. Graphics developed for 1235921395111 include:

- Riffle, Flatwater, Pool Habitat Types by Percent Occurrence
- Riffle, Flatwater, Pool Habitat Types by Total Length
- Total Habitat Types by Percent Occurrence
- Pool Types by Percent Occurrence
- Maximum Residual Depth in Pools
- Percent Embeddedness
- Mean Percent Cover Types in Pools
- Substrate Composition in Pool Tail-outs
- Mean Percent Canopy
- Dominant Bank Composition by Composition Type
- Dominant Bank Vegetation by Vegetation Type

HABITAT INVENTORY RESULTS

* ALL TABLES AND GRAPHS ARE LOCATED AT THE END OF THE REPORT *

The habitat inventory of June 11 to June 13, 2012 was conducted by A. Blessing and T. Anderson (WSP). The total length of the stream surveyed was 4,418 feet.

Stream flow was measured near the bottom of the survey reach with a Marsh-McBirney Model 2000 flowmeter at 0.36 cfs on June 12, 2012.

The unnamed tributary is an F4 channel type for 1,527 feet of the stream surveyed (Reach 1) and a G4 channel type for 2,891 feet of the stream surveyed (Reach 2). F4 channel types are entrenched meandering riffle/pool channels on low gradients with high width/depth ratios and gravel-dominant substrates. G4 channels are entrenched "gully" step-pool channels on moderate gradients with low width/depth ratios and gravel-dominant substrates.

Water temperatures taken during the survey period ranged from 51 to 55 degrees Fahrenheit. Air temperatures ranged from 51 to 64 degrees Fahrenheit.

Table 1 summarizes the Level II riffle, flatwater, and pool habitat types. Based on frequency of occurrence there were 44% pool units, 35% flatwater units, 14% riffle units, 5% dry units, 2% unsurveyed units, and 1% culvert units (Graph 1). Based on total length of Level II habitat types there were 50% flatwater units, 32% pool units, 7% riffle units, 6% dry units, 2% unsurveyed units, and 2% culvert units (Graph 2).

Nine Level IV habitat types were identified (Table 2). The most frequent habitat types by percent occurrence were mid-channel pool units, 36%; step run unit, 27%; and low gradient riffle units, 12% (Graph 3). Based on percent total length, step run units made up 47%, mid-channel pool units 26%, low gradient riffle units 6%, and dry units 6%.

A total of 57 pools were identified (Table 3). Main channel pools were the most frequently encountered at 93% (Graph 4), and comprised 97% of the total length of all pools (Table 3).

Table 4 is a summary of maximum residual pool depths by pool habitat types. Pool quality for salmonids increases with depth. Six of the 57 pools (11%) had a residual depth of two feet or greater (Graph 5).

The depth of cobble embeddedness was estimated at pool tail-outs. Of the 57 pool tail-outs measured, all of them had a value of 2 (100%) (Graph 6). On this scale, a value of 1 indicates the best spawning conditions and a value of 4 the worst. Additionally, a value of 5 was assigned to tail-outs deemed not suitable for spawning due to inappropriate substrate such as bedrock, log sills, boulders, or other considerations.

A shelter rating was calculated for each habitat unit and expressed as a mean value for each habitat type within the survey using a scale of 0-300. Riffle habitat types had a mean shelter rating of 3, flatwater habitat types had a mean shelter rating of 7, and pool habitats had a mean shelter rating of 30 (Table 1). Of the pool types, the main channel pools had a mean shelter rating of 30 and the scour pools had a mean shelter rating of 30 (Table 3).

Table 5 summarizes mean percent cover by habitat type. Small woody debris is the dominant cover type in the unnamed tributary. Graph 7 describes the pool cover in the unnamed tributary. Small woody debris is the dominant pool cover type followed by large woody debris.

Table 6 summarizes the dominant substrate by habitat type. Graph 8 depicts the dominant substrate observed in pool tail-outs. Gravel was the dominant substrate observed in 75% of the pool tail-outs. Sand was the next most frequently observed dominant substrate type and occurred in 21% of the pool tail-outs

The mean percent canopy density for the surveyed length of the unnamed tributary was 99%. One percent of the canopy was open. Of the canopy present, the mean percentages of hardwood and coniferous trees were 17% and 83%, respectively. Graph 9 describes the mean percent canopy in the unnamed tributary.

For the stream reach surveyed, the mean percent right bank vegetated was 100%. The mean percent left bank vegetated was 100%. The dominant elements composing the structure of the stream banks consisted of 90% sand/silt/clay, 9% cobble/gravel, and 1% boulders (Graph 10). Coniferous trees were the dominant vegetation type observed in 80% of the units surveyed. Additionally, 10% of the units surveyed had deciduous trees as the dominant vegetation type, and 10% had brush as the dominant vegetation type (Graph 11).

BIOLOGICAL INVENTORY RESULTS

Survey teams conducted a snorkel survey at nine sites for species composition and distribution in the unnamed tributary on September 26, 2012. The sites were sampled by I. Mikus and M. Groff (CDFW).

In Reach 1, which comprised the first 1,527 feet of stream, nine sites were sampled. The reach sites yielded nine young-of-the-year steelhead/rainbow trout (SH/RT), and three age 1+ SH/RT.

The following chart displays the information yielded from these sites:

| Date | Survey | Habitat | Habitat | Approx. | | SH/RT | | Coho | | |
|----------|----------|----------|---------|------------------------|--------|-------|----|------|----|--|
| Date | Site # | Unit # | Туре | Dist. from mouth (ft.) | YOY 1+ | | 2+ | YOY | 1+ | |
| Reach 1: | F4 Chann | nel Type | | | | | | | | |
| 09/26/12 | 1 | 009 | Pool | 322 | 6 | 0 | 0 | 0 | 0 | |
| | 2 | 010 | Pool | 373 | 1 | 0 | 0 | 0 | 0 | |
| | 3 | 013 | Pool | 476 | 2 | 1 | 0 | 0 | 0 | |
| | 4 | 019 | Pool | 742 | 0 | 1 | 0 | 0 | 0 | |
| | 5 | 023 | Pool | 871 | 0 | 0 | 0 | 0 | 0 | |
| | 6 | 029 | Pool | 1,101 | 0 | 0 | 0 | 0 | 0 | |
| | 7 | 041 | Pool | 1,437 | 0 | 0 | 0 | 0 | 0 | |
| | 8 | 043 | Pool | 1,489 | 0 | 0 | 0 | 0 | 0 | |
| | 9 | 044 | Pool | 1,527 | 0 1 0 | | 0 | 0 | 0 | |

2012 unnamed tributary to Redwood Creek underwater observations.

DISCUSSION

The unnamed tributary to Redwood Creek is an F4 channel type for the first 1,527 feet of stream surveyed and a G4 channel type for the remaining 2,891 feet. The suitability of F4 and G4 channel types for fish habitat improvement structures is as follows: F4 channel types are good for bank-placed boulders and fair for plunge weirs, single and opposing wing-deflectors, channel constrictors, and log cover. G4 channel types are good for bank-placed boulders and fair for plunge weirs, and log cover.

The water temperatures recorded on the survey days June 11 to June 13, 2012 ranged from 51 to 55 degrees Fahrenheit. Air temperatures ranged from 51 to 64 degrees Fahrenheit. This is a good water temperature range for salmonids. To make any conclusions, temperatures need to be monitored throughout the warm summer months, and more extensive biological sampling needs to be conducted.

Flatwater habitat types comprised 50% of the total length of this survey, riffles 7%, and pools 32%. Six of the 57 (11%) pools had a maximum residual depth greater than 2 feet. In general, pool enhancement projects are considered when primary pools comprise less than 40% of the length of total stream habitat. In first and second order streams, a primary pool is defined to have a maximum residual depth of at least two feet, occupy at least half the width of the low flow channel, and be as long as the low flow channel width. Installing structures that will increase or deepen pool habitat is recommended.

All of the 57 pool tail-outs measured had embeddedness ratings of 1 or 2. None of the pool tailouts had embeddedness ratings of 3 or 4. None of the pool tail-outs had a rating of 5, which is considered unsuitable for spawning. Cobble embeddedness measured to be 25% or less, a rating of 1, is considered to indicate good quality spawning substrate for salmon and steelhead.

Forty-five of the 57 pool tail-outs measured had gravel or small cobble as the dominant substrate. This is generally considered good for spawning salmonids.

The mean shelter rating for pools is 30. The shelter rating in the flatwater habitats is 7. A pool shelter rating of approximately 100 is desirable. The amount of cover that now exists is being provided primarily by small woody debris in the unnamed tributary. Small woody debris is the dominant cover type in pools followed by large woody debris. Log and root wad cover structures in the pool and flatwater habitats would enhance both summer and winter salmonid habitat. Log cover structures provide rearing fry with protection from predation, rest from water velocity, and also divide territorial units to reduce density related competition.

The mean percent canopy density for the stream was 99%. Reach 1 had a canopy density of 99% and Reach 2 had a canopy density of 99%. The percentage of right and left bank covered with vegetation was 100% and 100%, respectively.

RECOMMENDATIONS

- 1) The unnamed tributary to Redwood Creek should be managed as an anadromous, natural production stream.
- 2) The limited water temperature data available suggest that maximum temperatures are within the acceptable range for juvenile salmonids. To establish more complete and meaningful temperature regime information, 24-hour monitoring during the July and August temperature extreme period should be performed for 3 to 5 years.
- 3) Increase woody cover in the pools and flatwater habitat units. Most of the existing cover in the pools is from small woody debris. Adding high quality complexity with woody cover in the pools is desirable.

COMMENTS AND LANDMARKS

The following landmarks and possible problem sites were noted. All distances are approximate and taken from the beginning of the survey reach.

| Position (ft): | Habitat unit #: | Comments: |
|-------------------|--------------------|---|
| 0 | 0001.00 | Start of survey at the confluence with Redwood Creek. The channel is an F4. |
| 555 | 0015.00 | Woody debris is accumulating in the channel. |
| 760 | 0021.00 | Woody debris is accumulating in the channel. |
| 1150 | 0031.00 | There is a 0.5' high plunge. |
| 1489 | 0044.00 | Tributary #01 enters on the right bank. It contributes approximately 70% to the unnamed tributary's flow. The water temperature of the tributary is 51 degrees Fahrenheit, the water temperature downstream of the tributary is 51 degrees Fahrenheit, and the water temperature upstream of the confluence is 50 degrees Fahrenheit. For more information see the Unnamed Tributary to an Unnamed Tributary to Redwood Creek Stream Habitat Inventory Report |
| 1527 | 0045.00 | The channel changes from an F4 to a G4. |
| 1637 | 0049.00 | Log debris accumulation (LDA) #01 contains three pieces of large woody debris (LWD) and measures 3' high x 7' wide x 12' long. Water flows through the LDA and there are no visible gaps in it. Retained sediment ranges from silt to gravel and measures 4' wide x 8' long x 1.5' deep. Fish were not observed above the LDA. |
| 2311 | 0066.00 | There is a 0.5' high plunge. |
| 2652 | 0078.00 | LDA #02 contains two pieces of LWD and measures 4' high x 11' wide x 11' long. Water flows through the LDA and there are visible gaps in it. Retained sediment ranges from silt to gravel and measures 4' wide x 60' long x 1' deep. There is a 3' high plunge over the LDA. |
| 3903 | 0109.00 | LDA #03 contains three pieces of LWD and measures 5' high x 11.5' wide x 11' long. Water flows through the LDA and there are no visible gaps in it. Retained sediment ranges from silt to gravel and measures 4' wide x 8' long x 2' deep. |
| 4192 | 0125.00 | There is a 3' high plunge. |

- 4199 0126.00 Road 14900 crosses the channel. The crossing is a 5.5' high x 5.5' wide x 80' long corrugated metal culvert. The culvert has a slope of 3% and there is a 3' high plunge at the outlet. The maximum depth within 5' of the outlet is 1.6'. The middle of the culvert is misshapen and the bottom is rusty.
- 4405 0130.00 End of survey at LDA #04. Above the Road 14900 culvert, the slope increases from 3.3% to 11.6%. The channel is full of woody debris which is creating a series of jumps with shallow riffles and runs between them. There are few pools. LDA #04 contains four pieces of LWD and measures 10' high x 13' wide x 9' long. Water does not flow through the LDA and the channel is dry for 70' above it. There are no visible gaps in the LDA. Retained sediment ranges from gravel to boulders and measures 4' wide x 60' long x 3' deep. There is a 5' plunge from 1' diameter whole in the LDA. The maximum depth below the LDA is 0.6'.

REFERENCES

Flosi, G., Downie, S., Hopelain, J., Bird, M., Coey, R., and Collins, B. 1998. *California Salmonid Stream Habitat Restoration Manual*, 3rd edition. California Department of Fish and Game, Sacramento, California.

LEVEL III and LEVEL IV HABITAT TYPES

| RIFFLE Low Gradient Riffle High Gradient Riffle | (LGR) (HGR) | [1.1] [1.2] | $\{1\}$ $\{2\}$ |
|--|--|--|--|
| CASCADE Cascade Bedrock Sheet | (CAS) (BRS) | [2.1] [2.2] | { 3} {24} |
| FLATWATER Pocket Water Glide Run Step Run Edgewater | (POW) (GLD) (RUN) (SRN) (EDW) | [3.1] [3.2] [3.3] [3.4] [3.5] | {21} {14} {15} {16} {18} |
| MAIN CHANNEL POOLS Trench Pool Mid-Channel Pool Channel Confluence Pool Step Pool | (TRP) (MCP) (CCP) (STP) | [4.1] [4.2] [4.3] [4.4] | { 8 } {17} {19} {23} |
| SCOUR POOLS Corner Pool Lateral Scour Pool - Log Enhanced Lateral Scour Pool - Root Wad Enhanced Lateral Scour Pool - Bedrock Formed Lateral Scour Pool - Boulder Formed Plunge Pool | (CRP) (LSL) (LSR) (LSBk) (LSBo) (PLP) | [5.1] [5.2] [5.3] [5.4] [5.5] [5.6] | <pre>{22} {10} {10} {11} {12} {20} {9}</pre> |
| BACKWATER POOLS Secondary Channel Pool Backwater Pool - Boulder Formed Backwater Pool - Root Wad Formed Backwater Pool - Log Formed Dammed Pool | (SCP) (BPB) (BPR) (BPL) (DPL) | [6.1] [6.2] [6.3] [6.4] [6.5] | { 4 } { 5 } { 6 } { 7 } { 13 } |
| ADDITIONAL UNIT DESIGNATIONS Dry Culvert Not Surveyed Not Surveyed due to a marsh | (DRY) (CUL) (NS) (MAR) | [7.0] [8.0] [9.0] [9.1] | |

Table 1 - Summary of Riffle, Flatwater, and Pool Habitat Types

Stream Name: 1235921395111

130

LLID: 1235921395111 Drainage: Rockport

24114

14249

Survey Dates: 6/11/2012 to 6/13/2012

71

Confluence Location: Quad: SHERWOOD PEAK Legal Description: T19NR16WS12 Latitude: 39:30:40.0N Longitude: 123:35:32.0

4418

| Habitat Units | Units Fully Measured | Habitat Type | Habitat Occurrence (%) | Mean Length (ft.) | Total Length (ft.) | Total Length (%) | Mean Width (ft.) | Mean Depth (ft.) | Mean Max Depth (ft.) | Mean Area (sq.ft.) | Estimated Total Area (sq.ft.) | Mean Volume (cu.ft.) | Estimated Total Volume (cu.ft.) | Mean Residual Pool Vol (cu.ft.) | Mean Shelter Rating |
|------------------|-------------------------|-----------------|------------------------------|-------------------------|--------------------------|------------------------|------------------------|------------------------|-------------------------------|--------------------------|-------------------------------------|----------------------------|--|--|---------------------------|
| 1 | 0 | CULVERT | 0.8 | 80 | 80 | 1.8 | | | | | | | | | |
| 6 | 0 | DRY | 4.6 | 47 | 280 | 6.3 | | | | | | | | | |
| 45 | 9 | FLATWATER | 34.6 | 49 | 2223 | 50.3 | 5.6 | 0.3 | 0.7 | 261 | 11728 | 76 | 3420 | | 7 |
| 3 | 0 | NOSURVEY | 2.3 | 28 | 85 | 1.9 | | | | | | | | | |
| 57 | 57 | POOL | 43.8 | 25 | 1423 | 32.2 | 7.4 | 0.7 | 1.4 | 195 | 11135 | 184 | 10492 | 133 | 30 |
| 18 | 5 | RIFFLE | 13.8 | 18 | 327 | 7.4 | 5.1 | 0.2 | 0.4 | 69 | 1251 | 19 | 337 | | 3 |
| | | | | | | | | | | | | | | | |
| Total Units | Total L Fully Mea | Jnits asured | | Tota | al Length (ft.) | | | | | | Total Area (sq.ft.) | | Total Volume (cu.ft.) | 9 | |

Table 2 - Summary of Habitat Types and Measured Parameters

Stream Name: 1235921395111

LLID: 1235921395111 Drainage: Rockport

Survey Dates: 6/11/2012 to 6/13/2012

Confluence Location: Quad: SHERWOOD PEAK Legal Description: T19NR16WS12 Latitude: 39:30:40.0N Longitude: 123:35:32.0W

| Habitat Units | Units Fully Measured | Habitat Type | Habitat Occurrence (%) | Mean Length (ft.) | Total Length (ft.) | Total Length (%) | Mean Width (ft.) | Mean Depth (ft.) | Max Depth (ft.) | Mean Area (sq.ft.) | Estimated Total Area (sq.ft.) | Mean Volume (cu.ft.) | Estimated Total Volume (cu.ft.) | Mean Residual Pool Vol (cu.ft.) | Mean Shelter Rating | Mean Canopy (%) |
|------------------|-------------------------|-----------------|------------------------------|-------------------------|--------------------------|------------------------|------------------------|------------------------|-----------------------|--------------------------|-------------------------------------|----------------------------|--|--|---------------------------|-----------------------|
| 15 | 4 | LGR | 11.5 | 18 | 273 | 6.2 | 6 | 0.3 | 0.6 | 73 | 1090 | 21 | 309 | | 3 | 100 |
| 3 | 1 | HGR | 2.3 | 18 | 54 | 1.2 | 4 | 0.2 | 0.4 | 57 | 170 | 11 | 34 | | 5 | 100 |
| 10 | 3 | RUN | 7.7 | 16 | 163 | 3.7 | 6 | 0.5 | 0.9 | 110 | 1100 | 53 | 535 | | 7 | 100 |
| 35 | 6 | SRN | 26.9 | 59 | 2060 | 46.6 | 5 | 0.3 | 0.9 | 336 | 11757 | 87 | 3055 | | 7 | 98 |
| 47 | 47 | MCP | 36.2 | 24 | 1130 | 25.6 | 7 | 0.7 | 2.7 | 194 | 9105 | 185 | 8694 | 136 | 29 | 99 |
| 1 | 1 | CCP | 0.8 | 38 | 38 | 0.9 | 8 | 0.9 | 2.5 | 323 | 323 | 388 | 388 | 291 | 30 | 100 |
| 5 | 5 | STP | 3.8 | 41 | 206 | 4.7 | 7 | 0.5 | 1.8 | 285 | 1425 | 230 | 1151 | 143 | 42 | 100 |
| 4 | 4 | PLP | 3.1 | 12 | 49 | 1.1 | 6 | 0.6 | 1.3 | 71 | 283 | 65 | 260 | 45 | 30 | 100 |
| 6 | 0 | DRY | 4.6 | 47 | 280 | 6.3 | | | | | | | | | | |
| 1 | 0 | CUL | 0.8 | 80 | 80 | 1.8 | | | | | | | | | | |
| 3 | 0 | NS | 2.3 | 28 | 85 | 1.9 | | | | | | | | | | |

| Total Units | Total Units Fully Measured | Total Length (ft.) | Total Area (sq.ft.) | Total Volume (cu.ft.) | |
|----------------|-------------------------------|-----------------------|------------------------|--------------------------|--|
| 130 | 71 | 4418 | 25253 | 14424 | |

Table 3 - Summary of Pool Types

Stream Name: 1235921395111

LLID: 1235921395111 Drainage: Rockport

Survey Dates: 6/11/2012 to 6/13/2012

Confluence Location: Quad: SHERWOOD PEAK Legal Description: T19NR16WS12 Latitude: 39:30:40.0N Longitude: 123:35:32.0W

| Habitat Units | Units Fully Measured | Habitat Type | Habitat Occurrence (%) | Mean Length (ft.) | Total Length (ft.) | Total Length (%) | Mean Width (ft.) | Mean Residual Depth (ft.) | Mean Area (sq.ft.) | Estimated Total Area (sq.ft.) | Mean Residual Pool Vol (cu.ft.) | Estimated Total Resid.Vol. (cu.ft.) | Mean Shelter Rating | |
|------------------|-------------------------|-----------------|------------------------------|-------------------------|--------------------------|------------------------|------------------------|---------------------------------|--------------------------|-------------------------------------|--|--|---------------------------|--|
| 53 | 53 | MAIN | 93 | 26 | 1374 | 97 | 7.5 | 0.7 | 205 | 10852 | 140 | 7416 | 30 | |
| 4 | 4 | SCOUR | 7 | 12 | 49 | 3 | 6.1 | 0.6 | 71 | 283 | 45 | 180 | 30 | |

| Total | Total Units | Total Length | Total Area | Total Volume | |
|-------|----------------|--------------|------------|--------------|--|
| Units | Fully Measured | (ft.) | (sq.ft.) | (cu.ft.) | |
| 57 | 57 | 1423 | 11135 | 7597 | |

Table 4 - Summary of Maximum Residual Pool Depths By Pool Habitat Types

Stream Name: 1235921395111

LLID: 1235921395111 Drainage: Rockport

Survey Dates: 6/11/2012 to 6/13/2012

Confluence Location: Quad: SHERWOOD PEAK Legal Description: T19NR16WS12 Latitude: 39:30:40.0N Longitude: 123:35:32.0W

| Habitat Units | Habitat Type | Habitat Occurrence (%) | < 1 Foot Maximum Residual Depth | < 1 Foot Percent Occurrence | 1 < 2 Feet Maximum Residual Depth | 1 < 2 Feet Percent Occurrence | 2 < 3 Feet Maximum Residual Depth | 2 < 3 Feet Percent Occurrence | 3 < 4 Feet Maximum Residual Depth | 3 < 4 Feet Percent Occurrence | >= 4 Feet Maximum Residual Depth | >= 4 Feet Percent Occurrence |
|------------------|-----------------|------------------------------|--|-----------------------------------|--|-------------------------------------|--|-------------------------------------|--|-------------------------------------|---|------------------------------------|
| 47 | MCP | 82 | 8 | 17 | 34 | 72 | 5 | 11 | 0 | 0 | 0 | 0 |
| 1 | CCP | 2 | 0 | 0 | 0 | 0 | 1 | 100 | 0 | 0 | 0 | 0 |
| 5 | STP | 9 | 0 | 0 | 5 | 100 | 0 | 0 | 0 | 0 | 0 | 0 |
| 4 | PLP | 7 | 1 | 25 | 3 | 75 | 0 | 0 | 0 | 0 | 0 | 0 |

| Total | Total | Total | Total | Total | Total | Total | Total | Total | Total | Total |
|-------|------------|--------------|------------|--------------|------------|--------------|------------|--------------|------------|--------------|
| Units | < 1 Foot | < 1 Foot | 1< 2 Foot | 1< 2 Foot | 2< 3 Foot | 2< 3 Foot | 3< 4 Foot | 3< 4 Foot | >= 4 Foot | >= 4 Foot |
| | Max Resid. | % Occurrence |
| | Depth | | Depth | | Depth | | Depth | | Depth | |
| 57 | 9 | 16 | 42 | 74 | 6 | 11 | 0 | 0 | 0 | 0 |

Mean Maximum Residual Pool Depth (ft.): 1.4

Table 5 - Summary of Mean Percent Cover By Habitat Type

Drainage: Rockport Stream Name: 1235921395111 LLID: 1235921395111 Survey Dates: 6/11/2012 to 6/13/2012 Dry Units: 6 Confluence Location: Quad: SHERWOOD PEAK Legal Description: T19NR16WS12 Latitude: 39:30:40.0N Longitude: 123:35:32.0W Habitat Units Habitat Mean % LWD White Units Fully Туре Undercut SWD Root Mass Terr. Aquatic Boulders Bedrock Measured Banks Vegetation Vegetation Water Ledges LGR HGR TOTAL RIFFLE RUN SRN TOTAL FLAT MCP CCP STP PLP TOTAL POOL CUL NS TOTAL

Table 6 - Summary of Dominant Substrates By Habitat Type

| Stream N | lame: 12359 | 21395111 | | | | LLID | 1235921395111 | Drainage: | Rockport |
|------------------|-------------------------|-----------------|----------------------------------|-----------------------------|-------------------------------|-------------------------------------|-------------------------------------|--------------------------------|--------------------------------|
| Survey D | ates: 6/11/2 | 012 to 6/1 | 3/2012 | Dry Units | : 6 | | | | |
| Confluer | ce Location: | Quad: | SHERWOOD PEAK | Legal De | scription: T19N | R16WS12 Latitu | ide: 39:30:40.0N | Longitude: | 123:35:32.0W |
| Habitat Units | Units Fully Measured | Habitat Type | % Total Silt/Clay Dominant | % Total Sand Dominant | % Total Gravel Dominant | % Total Small Cobble Dominant | % Total Large Cobble Dominant | % Total Boulder Dominant | % Total Bedrock Dominant |
| 15 | 4 | LGR | 0 | 0 | 100 | 0 | 0 | 0 | 0 |
| 3 | 1 | HGR | 0 | 0 | 100 | 0 | 0 | 0 | 0 |
| 10 | 3 | RUN | 0 | 0 | 100 | 0 | 0 | 0 | 0 |
| 35 | 6 | SRN | 0 | 0 | 100 | 0 | 0 | 0 | 0 |
| 47 | 47 | MCP | 0 | 15 | 81 | 2 | 2 | 0 | 0 |
| 1 | 1 | CCP | 0 | 100 | 0 | 0 | 0 | 0 | 0 |
| 5 | 5 | STP | 0 | 0 | 100 | 0 | 0 | 0 | 0 |
| 4 | 4 | PLP | 0 | 50 | 50 | 0 | 0 | 0 | 0 |

Table 7 - Summary of Mean Percent Canopy for Entire Stream

| Stream Name: | 123592139511 | 1 | | | | LLID: 1235921395111 | Drainage: | Rockport |
|---------------------------|----------------------------|-----------------------------|-------------------------------|-------------------------------|--------------------------------|-----------------------|------------|--------------|
| Survey Dates: | 6/11/2012 to 6/ | 13/2012 | | | | | | |
| Confluence Loc | ation: Quad: | SHERWOOD P | EAK Legal I | Description: | T19NR16WS12 | Latitude: 39:30:40.0N | Longitude: | 123:35:32.0W |
| Mean Percent Canopy | Mean Percent Conifer | Mean Percent Hardwood | Mean Percent Open Units | Mean Right Bank % Cover | t Mean Left Bank % Cover | | | |
| 99 | 83 | 17 | 0 | 100 | 100 | | | |

Note: Mean percent conifer and hardwood for the entire reach are means of canopy components from units with canopy values greater than zero.

Open units represent habitat units with zero canopy cover.

Table 8 - Fish Habitat Inventory Data Summary

| Stream Name: | 123592 | 139511 | 1 | | | | LLID: 1235921395111 | Drainage: R | lockport |
|----------------|---------|----------|---------------|----------------------|----------|------|-----------------------|-------------|--------------|
| Survey Dates: | 6/11/20 | 12 to 6/ | 13/2012 | Survey Length (ft.): | 4418 | Main | Channel (ft.): 4418 | Side Chann | nel (ft.): 0 |
| Confluence Loc | ation: | Quad: | SHERWOOD PEAK | Legal Description: | T19NR16W | S12 | Latitude: 39:30:40.0N | Longitude: | 123:35:32.0W |

Summary of Fish Habitat Elements By Stream Reach

| STREAM REACH: 1 | | |
|--|---|---|
| Channel Type: F4 | Canopy Density (%): 98.8 | Pools by Stream Length (%): 61.7 |
| Reach Length (ft.): 1527 | Coniferous Component (%): 77.9 | Pool Frequency (%): 56.8 |
| Riffle/Flatwater Mean Width (ft.): 7.4 | Hardwood Component (%): 22.1 | Residual Pool Depth (%): |
| BFW: | Dominant Bank Vegetation: Coniferous Trees | < 2 Feet Deep: 80 |
| Range (ft.): 8 to 11 | Vegetative Cover (%): 99.8 | 2 to 2.9 Feet Deep: 20 |
| Mean (ft.): 10 | Dominant Shelter: Small Woody Debris | 3 to 3.9 Feet Deep: 0 |
| Std. Dev.: 1 | Dominant Bank Substrate Type: Sand/Silt/Clay | >= 4 Feet Deep: 0 |
| Base Flow (cfs.): 0.4 | Occurrence of LWD (%): 35 | Mean Max Residual Pool Depth (ft.): 1.5 |
| Water (F): 51 - 55 Air (F): 51 - 64 | LWD per 100 ft.: | Mean Pool Shelter Rating: 33 |
| Dry Channel (ft): 0 | Riffles: 2 | |
| | Pools: 9 | |
| | Flat: 2 | |
| Pool Tail Substrate (%): Silt/Clav: 0 Sa | nd: 28 Gravel: 68 Sm Cobble: 4 La Cobble: 0 | Boulder: 0 Bedrock: 0 |
| | | |
| | . 100.0 3. 0.0 4. 0.0 3. 0.0 | |
| STREAM REACH: 2 | | |
| Channel Type: G4 | Canopy Density (%): 99.2 | Pools by Stream Length (%): 16.6 |
| Reach Length (ft.): 2891 | Coniferous Component (%): 86.9 | Pool Frequency (%): 37.2 |
| Riffle/Flatwater Mean Width (ft.): 4.6 | Hardwood Component (%): 13.1 | Residual Pool Depth (%): |
| BFW: | Dominant Bank Vegetation: Coniferous Trees | < 2 Feet Deep: 97 |
| Range (ft.): 6 to 11 | Vegetative Cover (%): 99.9 | 2 to 2.9 Feet Deep: 3 |
| Mean (ft.): 8 | Dominant Shelter: Small Woody Debris | 3 to 3.9 Feet Deep: 0 |
| Std. Dev.: 2 | Dominant Bank Substrate Type: Sand/Silt/Clay | >= 4 Feet Deep: 0 |
| Base Flow (cfs.): 0.4 | Occurrence of LWD (%): 23 | Mean Max Residual Pool Depth (ft.): 1.2 |
| Water (F): 51 - 52 Air (F): 51 - 62 | LWD per 100 ft.: | Mean Pool Shelter Rating: 27 |
| Dry Channel (ft): 280 | Riffles: 8 | |
| | Pools: 10 | |
| | 1 0013. 10 | |
| | Flat: 2 | |
| Pool Tail Substrate (%): Silt/Clav: 0 Sa | Flat: 2 nd: 16 Gravel: 81 Sm Cobble: 3 I g Cobble: 0 | Boulder: 0 Bedrock: 0 |
| Pool Tail Substrate (%): Silt/Clay: 0 Sa | Flat: 2 nd: 16 Gravel: 81 Sm Cobble: 3 Lg Cobble: 0 | Boulder: 0 Bedrock: 0 |

Table 9 - Mean Percentage of Dominant Substrate and Vegetation

| Stream Name: | 1235921395111 | | | | | LLID: 1235921 | 395111 | Drainage: | Rockport |
|----------------|---------------|-----------|---------------|--------------------|-------------|----------------|---------|------------|--------------|
| Survey Dates: | 6/11/20 | 12 to 6/1 | 13/2012 | | | | | | |
| Confluence Loc | ation: | Quad: | SHERWOOD PEAK | Legal Description: | T19NR16WS12 | Latitude: 39:3 | 0:40.0N | Longitude: | 123:35:32.0W |

2

Mean Percentage of Dominant Stream Bank Substrate

| Dominant Class of Substrate | Number of Units Right Bank | Number of Units Left Bank | Total Mean Percent (%) |
|--------------------------------|-------------------------------|------------------------------|---------------------------|
| Bedrock | 0 | 0 | 0.0 |
| Boulder | 1 | 0 | 0.7 |
| Cobble / Gravel | 6 | 7 | 9.2 |
| Sand / Silt / Clay | 64 | 64 | 90.1 |

Mean Percentage of Dominant Stream Bank Vegetation

| Dominant Class of Vegetation | Number of Units Right Bank | Number of Units Left Bank | Total Mean Percent (%) |
|---------------------------------|-------------------------------|------------------------------|---------------------------|
| Grass | 0 | 0 | 0.0 |
| Brush | 7 | 7 | 9.9 |
| Hardwood Trees | 8 | 6 | 9.9 |
| Coniferous Trees | 56 | 58 | 80.3 |
| No Vegetation | 0 | 0 | 0.0 |

Total Stream Cobble Embeddedness Values:

Table 10 - Mean Percent of Shelter Cover Types For Entire Stream

StreamName: 1235921395111

LLID: 1235921395111 Drainage: Rockport

Survey Dates: 6/11/2012 to 6/13/2012

Confluence Location: Quad: SHERWOOD PEAK Legal Description: T19NR16WS12 Latitude: 39:30:40.0N Longitude: 123:35:32.0W

| | Riffles | Flatwater | Pools |
|----------------------------|---------|-----------|-------|
| | | | |
| UNDERCUT BANKS (%) | 0 | 19 | 13 |
| SMALL WOODY DEBRIS (%) | 53 | 57 | 48 |
| LARGE WOODY DEBRIS (%) | 0 | 2 | 34 |
| ROOT MASS (%) | 0 | 1 | 2 |
| TERRESTRIAL VEGETATION (%) | 0 | 12 | 0 |
| AQUATIC VEGETATION (%) | 0 | 0 | 0 |
| WHITEWATER (%) | 0 | 0 | 2 |
| BOULDERS (%) | 47 | 9 | 1 |
| BEDROCK LEDGES (%) | 0 | 0 | 0 |

UNNAMED TRIBUTARY TO REDWOOD CREEK 2012 HABITAT TYPES BY PERCENT OCCURRENCE



UNNAMED TRIBUTARY TO REDWOOD CREEK 2012 HABITAT TYPES BY PERCENT TOTAL LENGTH



UNNAMED TRIBUTARY TO REDWOOD CREEK 2012 HABITAT TYPES BY PERCENT OCCURRENCE



UNNAMED TRIBUTARY TO REDWOOD CREEK 2012 POOL TYPES BY PERCENT OCCURRENCE



UNNAMED TRIBUTARY TO REDWOOD CREEK 2012 MAXIMUM DEPTH IN POOLS



UNNAMED TRIBUTARY TO REDWOOD CREEK 2012 PERCENT EMBEDDEDNESS



UNNAMED TRIBUTARY TO REDWOOD CREEK 2012 MEAN PERCENT COVER TYPES IN POOLS





UNNAMED TRIBUTARY TO REDWOOD CREEK 2012 SUBSTRATE COMPOSITION IN POOL TAIL-OUTS



UNNAMED TRIBUTARY TO REDWOOD CREEK 2012 MEAN PERCENT CANOPY



UNNAMED TRIBUTARY TO REDWOOD CREEK 2012 DOMINANT BANK COMPOSITION IN SURVEY REACH



UNNAMED TRIBUTARY TO REDWOOD CREEK 2012 DOMINANT BANK VEGETATION IN SURVEY REACH



