


- Barrier Remediated
- Total Barrier
- Partial Barrier
- Not a Barrier
- Remediated, Fish Response Unconfirmed
- ▲ Natural Total Barrier
- ▲ Natural Partial Barrier
- ★ Screened Diversion
- ☆ Unscreened Diversion
- Unknown Passage Status
- Unassessed

Before Photo
Not Available



Site Name: Joe Sanchez Farms
Stream Name: Steamboat Slough
Structure Owner: Private landowner(s) (non-corporate)
Year Remediated: 2013
Site Type: Diversion
Site Status After Remediation: Screened
Species Benefited After Remediation: Chinook salmon
Immediate Downstream barrier PAD ID:
Notes: Screened to 24 cfs by FWA in May 2013.

PAD ID: 700641
Tributary To: Cache Slough
Barrier Remediation By: Family Water Alliance
Barrier Description Prior to Remediation: Unscreened
Count of Barriers Downstream:
Count of Barriers Upstream:
Distance Upstream to Next Barrier or Limit of Anadromy : mi

*Site statistics based on December 2014 version of the Passage Assessment Database